

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010401/EVY3N2**Date:** 27/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00139422000

Claimant Vehicle No : SKL919G **Insured Vehicle No :** SKP8275G

Date of Loss: 07/10/2021 Nature of Claim: TP Claim No: SNM21D205753/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKL919G**

Make & Model: MERCEDES-BENZ E250, 1.8 (A) Engine No: 27186030481717

Reg. Date: 17/01/2013 (Man. Year: 2012) Chassis No: WDD2120472A654276

Colour: Grey Odometer: 78419 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/55R18 Rear Tyre Size: 265/55R18

Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm

Front Right Side: Pirelli 4 mm Rear Right Side: Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,366.32	3,321.48	4,044.84	54.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	1,000.00	1,550.00	60.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,916.32	4,321.48	5,594.84	56.42
Approved Total (Overridden) (\$\$)		3,450.00		
Nett Amount (\$\$)	9,916.32	3,450.00	6,466.32	65.21

INSPECTION

Date of Assignment: 14/10/2021

Date Inspected: 12/10/2021 Inspected At: Ricky Teo Battery & Tyres Trading (HQ)
Blk1002 Bukit Merah Lane 3, #01-79
Singapore 159719

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Oct 2021)
Parts:	143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL919G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,490.60 FL	*1,355.00 FL
2	1		*REAR BUMPER LOWER	Cut	560.80 FL	*489.00 FL
3	2		*REAR BUMPER SIDE GUIDE LH & RH	Broken	173.00 FL	*173.00 FL
4	1		*REAR BUMPER LOWER BRACKET LH & RH	N/s Broken	82.40 FL	*41.20 FL
5	1		*REAR BUMPER CENTRE BRACKET	Broken	159.00 FL	*159.00 FL
6	1		*REAR BUMPER TOW COVER	Not Necessary	68.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Dented	860.00 FL	*780.00 FL
8	1		*REAR END PANEL	Repair	1,440.00 FL	*- FL
9	1		*REAR END PANEL INNER GARNISH	Not Necessary	255.00 FL	*- FL
10	1		*REAR PDC SENSOR SPACER RING (4X)	Necessary	90.00 FL	*40.00 FL
11	2		*REAR TAILLAMP LH & RH	Not Necessary	1,486.00 FL	*- FL
12	2		*REAR TAILLAMP BRACKET LH & RH	Broken	160.00 FL	*120.00 FL
13	1		*REAR PDC SENSOR (4X)	Shorted (2 Pcs only)	1,160.00 FL	*500.00 FL
14	1		*REAR BUMPER CLIPS & RIVETS	Necessary	80.00 FS	*30.00 FS
15	1		*PANEL JOINT SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,164.80	3,687.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	798.48	365.72
Total Parts (\$\$)	7,366.32	3,321.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE/REFIT/REPAIR & REPLACE AFFECTED PARTS	New	1,000.00	400.00
2	SPRAY PAINT ON THE AFFECTED PORTION	New	700.00	400.00
3	LABOUR TO REMOVE/REPLACE/REFIX REAR UPHOLSTERY	New	200.00	30.00
4	LABOUR TO INSTALL REVERSE SENSOR	New	100.00	30.00
5	TO CONDUCT WIRING CHECK FOR REAR PORTION	New	50.00	30.00
6	TO APPLY ANTI RUST COATING	New	200.00	30.00
7	TO PERFORM SYSTEM DIAGNOSTIC & RESET ECU	New	300.00	80.00
Gross Labour Cost (\$\$)			2,550.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >