

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21010402/UEA3Q2**Date:** 18/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070106487
Claimant Vehicle No :	GBE7261S	Insured Vehicle No :	GBJ6894X
Date of Loss:	09/10/2021	Nature of Claim:	TP
		Claim No:	0426071881SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE7261S		
Make & Model:	NISSAN NV350, 2.5 5AT 5DR EURO V (A)	Engine No:	YD25349364A
Reg. Date:	18/07/2014 (Man. Year: 2014)	Chassis No:	JN1MC2E26Z0002120
Colour:	White	Odometer:	242239 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	WINTURN 6 mm	Rear Left Side:	WINTURN 6 mm
Front Right Side:	WINTURN 6 mm	Rear Right Side:	WINTURN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,949.70	1,812.70	137.00	7.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	690.00	390.00	36.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,029.70	2,502.70	527.00	17.39
Approved Total (Overridden) (\$\$)		2,000.00		
Nett Amount (\$\$)	3,029.70	2,000.00	1,029.70	33.99
+ Loss of Use (3.0 x S\$100.00/day) (\$\$)		300.00		
		(S\$)	2,300.00	
Liabe Amount (50.00%) (\$\$)		1,150.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		1,157.45		
Global Sum Settlement (\$\$)		1,150.00		

INSPECTION

Date of Assignment:	11/10/2021	Quan De Motor Trading BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY SINGAPORE 417883 Singapore 417883
Date Inspected:	11/10/2021 Inspected At:	
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,742.00 FN	*1,742.00 FN
2	1		*TAILGATE NV 350 EMBLEM	Necessary	59.70 FN	*59.70 FN
3	1		*TAILGATE URVAN EMBLEM	Necessary	101.30 FN	*101.30 FN
4	2		*TAILGATE HINGES	Serviceable	130.00 FN	*- FN
5	1		*TAILGATE 70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
6	1		*TAILGATE 5 PAX STICKER	Necessary	10.00 FS	*10.00 FS
7	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
8	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	2,153.00	2,003.00
- Nett Item Discount on N Items 10.00/10.00% (\$)	203.30	190.30
Total Parts (\$)	1,949.70	1,812.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	100.00	40.00
3	LABOUR FOR PANEL BEATING ,WELDING & RENEW PARTS	New	480.00	250.00
4	SPRAY PAINTING	New	450.00	380.00
Gross Labour Cost (\$\$)			1,080.00	690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >