

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: GBC 726LS
at Workshop m/s Quan An
of G3J 6894X
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$24k.
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 2 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: LYA 810168

Date / Time Action / Instruction Rep 8k.

Veh No: GBC 726LS Yr Regn: 18/7/14
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA/
Make: Nissan NV350 c.c. 2488
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 242239 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JN1MC2E2620002120
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195R15
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Winturn

Front 6 Rear 6
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 9/10/21 D.O.I. 11/10/21
Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

rear tailgate
The U/C / Chassis frame / Body Structure affected due to collision.

4/5 @ 2000 confirmed w. h Jennifer

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)

) __ \$ + RS __ \$

☐ : Interview (\$)

) Photos

☐ : Tech. Invs (\$)

) Others

☐ : Weekend (\$)

)

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67

AUTOBAY, SINGAPORE 417883

HP: 96709191

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Department

not Admitted
RKR
1/5 \$2000/
2 Lys.
11/10/21

Date: 11 October 2021

**Accident on 09/10/2021 involving vehicles GBE7261S & GBJ6894X
along Lorong 24A Geylang**

Estimate cost of repair to vehicle GBE7261S Nissan NV350 Van

Nett Items:

1 pc.	tailgate	Body RD	\$ 1,742.00 ✓
1 pc.	tailgate 'NV350' emblem	NR	\$ 59.70 ✓
1 pc.	tailgate 'Urvan' emblem	NR	\$ 101.30 ✓
2 pcs.	tailgate hinges @ \$65.00	SVC	\$ 130.00 X
			<u>\$ 2,033.00</u>
Less 10%			\$ 203.30
			<u>\$ 1,829.70</u>

S. Nett Items:

1 pc.	tailgate '70 KM/H' sticker	NR	\$ 10.00 ✓
1 pc.	tailgate '5 pax' sticker	NR	\$ 10.00 ✓
1 pc.	rear windscreen sealant	NR	\$ 50.00 40
1 pc.	rear windscreen inner seal	NR	\$ 50.00 40

Labour Charges:

To check wiring	\$ 50.00 20
To spray rust proofing	\$ 100.00 40
Labour for panel beating, welding & renew parts	\$ 480.00 250
Spray painting	\$ 450.00 300

Total: \$ 3,029.70

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1903
102
P-17127
SN-100
L 690
25027