

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CS/CTI21010408/BTY3Q2

Date:

16/11/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No: DMB1SNA00008512001

Claimant Vehicle No : SMV3844S**Insured Vehicle No :** PC8190B

Date of Loss: 30/08/2021

Nature of Claim: TP

Claim No: SNM21D205752/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMV3844S**

Make & Model: TOYOTA COROLLA, 1.8 HYBRID GX CVT (A)

Engine No: 2ZR2C27500

Reg. Date: 28/09/2020 (Man. Year: 2018)

Chassis No: JTNK93BE003003614

Colour: Blue

Odometer: 67988 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,493.53	6,443.12	4,050.41	38.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	720.00	2,180.00	75.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,393.53	7,163.12	6,230.41	46.52
Approved Total (Overridden) (S\$)		5,700.00		

(S\$)	13,393.53	5,700.00	7,693.53	57.44
+ GST 7.00/7.00% (S\$)	937.55	399.00	538.55	57.44
Nett Amount (S\$)	14,331.08	6,099.00	8,232.08	57.44

INSPECTION

Date of Assignment:	11/10/2021		
Date Inspected:	12/10/2021	Inspected At:	160 SIN MING DR #01-14 Repairer: Team Autopro Pte Ltd (Sin Ming)
Estimated Period of Repair:	4.0 days		

Adjuster:	Lim Teow Guan	Manager:	DENISE TAY KWEE CHENG
-----------	---------------	----------	-----------------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2021)
Parts:	143	TOYOTA COROLLA 1.8 HYBRID GX CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV3844S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,084.60 FL	*845.10 FL
2	2		*FRONT BUMPER SIDE RETAINER	Necessary	178.52 FL	*70.00 FL
3	1		*FRONT BUMPER INNER SPONGE	Not Damaged	238.45 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	489.60 FL	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Broken	681.30 FL	*195.00 FL
6	2		*FRONT BUMPER LOWER GRILLE OUTER GARNISH	Broken	579.20 FL	*315.60 FL
7	1		*FRONT BUMPER LISENCE PLATE	Not Damaged	84.20 FL	*- FL
8	1		*FRONT GRILLE	Broken	415.00 FL	*415.00 FL
9	1		*FRONT RADAR SENSOR	Scratched	1,812.80 FL	*1,812.80 FL
10	1		*FRONT RADAR SENSOR BRACKET	Not Damaged	254.00 FL	*- FL
11	1		*FRONT SUPPORT PANEL	Not Damaged	862.70 FL	*- FL
12	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Damaged	248.60 FL	*- FL
13	2		*HEADLAMP	Broken	4,972.40 FL	*4,044.00 FL
14	2		*HEADLAMP LOWER BRACKET	Not Damaged	210.00 FL	*- FL
15	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
16	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
17	1		*FRONT BUMPER WRAP STICKER	Necessary	550.00 FS	*550.00 FS
18	1		*FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
19	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
20	1		*FRONT GRILLE LOGO	Cut	180.00 FS	*90.00 FS
21	1		*FRONT GRILLE WRAP STICKER	Not Necessary	180.00 FS	*- FS
22	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
23	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
24	1		*FRONT NUMBER PLATE W/CASING	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)

13,521.37

8,367.50

- List Item Discount on L Items 25.00/25.00% (\$\$)

3,027.84

1,924.38

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (\$\$)	10,493.53
						6,443.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING	New	100.00	0.00
2	DIAGNOSTIC & RESET FAULT CODE	New	300.00	120.00
3	ALIGNMENT RADAR SENSOR	New	300.00	0.00
4	PANEL BEATING	New	1,000.00	400.00
5	RUST PROOFING	New	200.00	0.00
6	SPRAY PAINTING	New	1,000.00	200.00
Gross Labour Cost (S\$)			2,900.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >