

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21010410/UTF3N2**Date:** 30/11/2021**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001744264
Claimant Vehicle No :	XD614Z	Insured Vehicle No :	XD7044Y
Date of Loss:	08/10/2021	Nature of Claim:	TP
		Claim No:	263788

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD614Z	Engine No:	6D24384864
Make & Model:	MITSUBISHI FV51JKM4RDEA, 12.9 D (M)	Chassis No:	FV517KA00142
Reg. Date:	15/09/2006 (Man. Year: 2006)	Odometer:	942829 km
Colour:	White		
Engine Capacity:	11945 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80R22.5	Rear Tyre Size:	295/80R22.5(D/D)
Front Left Side:	HILO 6 mm	Rear Left Side:	HILO 6/66/6 mm
Front Right Side:	HILO 6 mm	Rear Right Side:	HILO 6/66/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,509.98	2,586.49	6,923.49	72.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,220.00	1,760.00	59.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,489.98	3,806.49	8,683.49	69.52
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	12,489.98	3,000.00	9,489.98	75.98
+ GST 7.00/7.00% (S\$)	874.30	210.00	664.30	75.98
Nett Amount (S\$)	13,364.28	3,210.00	10,154.28	75.98

INSPECTION

Date of Assignment:	11/10/2021	
Date Inspected:	12/10/2021	Inspected At: Mah Lian Motor Vehicle Repairer (HQ) NO. 38 DEFU LANE 9 Singapore 539278
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Nov 2021)	
Parts:	N/A	MITSUBISHI FV51JKM4RDEA 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD614Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Broken	2,213.37 FL	*2,213.37 FL
2	1		*FRONT CORNER PANEL-LH	Repair	852.68 FL	*- FL
3	1		*FRONT CORNER PANEL SEAL-LH	Not Necessary	85.78 FL	*- FL
4	1		*FRONT DOOR ASSY-LH	Repair	4,567.80 FL	*- FL
5	1		*FRONT DOOR GARNISH-LH	Not Necessary	120.86 FL	*- FL
6	1		*FRONT SIDE LAMP-LH	Not Necessary	255.53 FL	*- FL
7	1		*FRONT SIDE LAMP RIM-LH	Not Necessary	252.34 FL	*- FL
8	1		*STEP PANEL LOWER-LH	Not Necessary	403.49 FL	*- FL
9	1		*FRONT BUMPER	Not Necessary	2,088.37 FL	*- FL
10	1		*FRONT BUMPER SIDE GARNISH	Not Necessary	120.53 FL	*- FL
11	1		*SIDE MIRROR STAY-LH	Distorted	708.59 FL	*708.59 FL
12	1		*SIDE MIRROR LOWER BRACKET-LH	Distorted	134.03 FL	*134.03 FL
13	1		*FRONT WINDSCREEN GLASS RUBBER (\$589.00)(50%)	Torn	657.45 FS	*294.50 FS
					Sub Total (\$\$)	12,460.82 3,350.49
					- List Item Discount on L Items 25.00/25.00% (\$\$)	2,950.84 764.00
					Total Parts (\$\$)	9,509.98 2,586.49

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT FRONT WINDSCREEN GLASS,RUBBER SEAL	New	120.00	120.00
2	LABOUR TO CONNECT & REFOCUS ALL LIGHT	New	280.00	0.00
3	LABOUR TO REMOVE & DISMANTLE & WELD & REFIT ALL ABOVE PARTS	New	1,300.00	600.00
4	TO RUST PROOFING AT AFFECTED AREA	New	380.00	0.00
5	TO SPRAY & PAINTING AT ACCIDENT AFFECTED AREA	New	900.00	500.00
Gross Labour Cost (\$)			2,980.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >