

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 17 Nov 2021

Preliminary Advice

Insured Vehicle No : XD7044Y

TP Vehicle No : XD614Z

Make : MITSUBISHI FV51JKM4RDEA

Date of Inspection : 12/10/2021

Inspection At : MAH LIAN MOTOR VEHICLE REPAIRER (HQ)
NO. 38 DEFU LANE 9
SINGAPORE 539278

Accident Date : 08/10/2021

Assignment Date : 11/10/2021

Est. Duration of Repair : 3

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,489.98
Revised Amount	:S\$	12,489.98
Check Items (Estimated)	:S\$	0.00
Total	:S\$	12,489.98

Lump Sum Repair	:S\$	3,000.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	58,000.00
COE / PARF Rebate	:S\$	19,304.00
Salvage Value	:S\$	
Margin for Repair	:S\$	38,696.00

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (x) Lump Sum repair

- (x) The above survey was conducted on a 'without prejudice' basis.