3/7/22, 1:07 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21010413/TQY3N2

07/03/2022 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00021102102

**Claimant Vehicle** 

SJQ6781G

Insured Vehicle YP6171U

No:

Date of Loss:

02/10/2021

No:

Claim No:

SNM21D205673/C02/CSC

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SJQ6781G Reg No:

Make & Model: HONDA FIT, 1.3 G (A) Engine No: L13A4191361 Reg. Date: 21/05/2009 (Man. Year: 2009) Chassis No: GE61174792 135114 km Colour: White Odometer:

Nature of Claim: TP

**Engine Capacity:** 1339 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 195/50R16 Rear Tyre Size: 195/50R16 Front Left Side: Rear Left Side: Goodvear 6 mm Goodvear 6 mm Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,866.16	488.90	2,377.26	82.94
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,560.00	700.00	1,860.00	72.66
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	5,426.16	1,188.90	4,237.26	78.09
Ap	proved Total (Overridden) (S\$)		950.00		
	Nett Amount (S\$)	5,426.16	950.00	4,476.16	82.49

**INSPECTION** 

Date of Assignment: 13/10/2021

Yi Heng Motor Workshop (HQ) Date Inspected: 12/10/2021 Inspected At: Blk 1 Kaki Bt Ave 6 #02-19

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

3/7/22, 1:07 PM Adjuster Report

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Mar 2022)

Parts: 144 HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJQ6781G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN MOULDING	Not Necessary	187.00 FL	*-FL
2	1		*FRONT BUMPER	Not Necessary	583.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER (LH)	Not Necessary	89.00 FL	*- FL
4	1		*WIPER GRILLE (LH)	Cut	110.50 FL	*110.50 FL
5	1		*FRONT FENDER (LH)	Bent	587.00 FL	*375.62 FL
6	1		*FRONT FENDER COWLING (LH)	Not Necessary	216.00 FL	*- FL
7	10		*FRONT FENDER COWLING CLIPS (LH)	Not Necessary	65.00 FL	*- FL
8	1		*FRONT FENDER QUARTER GARNISH (LH)	Cut	271.00 FL	*125.00 FL
9	1		*FRONT FENDER QUARTER GLASS MOULDING (LH)	Not Necessary	176.00 FL	*- FL
10	1		*FRONT DOOR A PILLAR (LH)	Not Necessary	685.20 FL	*- FL
11	1		*FRONT WHEEL HOUSING PANEL (LH)	Repair	313.00 FL	*- FL
12	1		*FRONT FENDER QUARTER GLASS GUM	Not Necessary	60.00 FS	*-FS
13	1		*FRONT FENDER WHEEL HOUSING PANEL SEALANT	Not Necessary	60.00 FS	*- FS
14	1		*FRONT WINDSCREEN INNERSEAL	Not Necessary	60.00 FS	*-FS
15	1		*FRONT WINDSCREEN GUM	Not Necessary	60.00 FS	*-FS
F=Fra	ınchise	part. S=Spcl	Nett. L=ListItemDisc.			
				Sub Total (S\$)	3,522.70	611.12
			- List Item Discount on L Item	ns 20.00/20.00% (S\$)	656.54	122.22
				Total Parts (S\$)	2,866.16	488.90
			Report was unsubmitted during this pri	int-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO APPLY UNDER SEALING ON AFFECTED AREAS	New	120.00	0.00
2	TO REMOVE & REFIX FRONT WINDSCREEN	New	280.00	0.00
3	TO REMOVE & REFIX FRONT QUARTER GLASS (LH)	New	180.00	0.00
4	TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC	New	1,320.00	300.00
5	TO RESPRAY ON AFFECTED AREAS	New	660.00	400.00
		Gross Labour Cost (S\$)	2,560.00	700.00
	Report was unsubm	nitted during this print-out.		

< END OF ESTIMATES >