

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010414/KPA3Q2**Date:** 17/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210060980
Claimant Vehicle No :	SLJ3747P	Insured Vehicle No :	SNA5222Y
Date of Loss:	09/10/2021	Nature of Claim:	TP
		Claim No:	5009937451SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ3747P	Engine No:	L15B4030743
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11110740
Reg. Date:	07/12/2016 (Man. Year: 2015)	Odometer:	37952 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,895.60	4,471.28	1,424.32	24.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,110.00	1,730.00	380.00	18.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,005.60	6,201.28	1,804.32	22.54
Approved Total (Overridden) (S\$)		4,950.00		
(S\$)	8,005.60	4,950.00	3,055.60	38.17
+ GST 7.00/7.00% (S\$)	560.39	346.50	213.89	38.17
Nett Amount (S\$)	8,565.99	5,296.50	3,269.49	38.17
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,718.50		

INSPECTION

Date of Assignment:	11/10/2021	
Date Inspected:	12/10/2021	Inspected At: City Auto Pte Ltd (Sin Ming) (HQ) Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est Singapore 575643
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	927.40 FL	*523.10 FL
2	1		*FRONT BUMPER RETAINER	O/S Cracked	39.20 FL	*19.60 FL
3	1		*FRONT BUMPER REINFORCEMENT	Repair	321.40 FL	*- FL
4	1		*FRONT BUMPER LOWER	Buckled / Dented	212.70 FL	*212.70 FL
5	1		*RH HEADLAMP	Cracked	1,923.40 FL	*1,810.50 FL
6	1		*RH HEADLAMP LOWER BRACKET	Cracked	39.40 FL	*39.40 FL
7	1		*FRONT RH FENDER	Bent	521.40 FL	*521.40 FL
8	1		*FRONT RH FENDER BRACE BRACKET	Bent	58.40 FL	*58.40 FL
9	1		*FRONT RH FENDER INNERSHIELD	Cracked	130.20 FL	*130.20 FL
10	10		*FRONT RH FENDER INNERSHIELD CLIP	Necessary	35.00 FL	*35.00 FL
11	1		*FRONT RH FENDER WHEEL ARCH GARNISH	Dented	130.20 FL	*130.20 FL
12	1		*BONNET	Bent	884.20 FL	*884.20 FL
13	2		*BONNET HINGE	Repair	97.00 FL	*- FL
14	1		*BONNET INSULATOR	Cracked	122.40 FL	*122.40 FL
15	1		*WASHER TANK	Dented	75.90 FL	*75.90 FL
16	1		*WASHER MOTOR	Cracked	89.20 FL	*89.20 FL
17	1		*WASHER FILLER NECK	Serviceable	27.40 FL	*- FL
18	1		*WASHER FILLER CAP	Missing	16.50 FL	*16.50 FL
19	1		*FRONT GRILLE BASE	Serviceable	281.40 FL	*- FL
20	1		*FRONT GRILLE COVER	Serviceable	203.20 FL	*- FL
21	1		*FRONT GRILLE BRACKET -RH	Serviceable	47.40 FL	*- FL
22	1		*RH FOG COVER	Dented	25.70 FL	*25.70 FL
23	1		*FRONT RH RIM	Dented	640.96 FS	*550.00 FS
24	1		*FRONT RH FENDER INNER EXTENSION PANEL	Bent	165.20 FL	*165.20 FL
25	1		*FRONT RH FENDER INNER GUSSEL PANEL (IN)	Repair	89.70 FL	*- FL
26	1		*FRONT RH FENDER INNER GUSSEL PANEL (OUT)	Repair	62.40 FL	*- FL
27	12		*BUMPER CLIP	Necessary	42.00 FL	*42.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,209.26	5,451.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,313.66	980.32
Total Parts (\$\$)	5,895.60	4,471.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND LIGHTING	New	50.00	20.00
2	TO CONDUCT WHEEL ALIGNMENT	New	60.00	60.00
3	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS	New	800.00	650.00
4	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	1,200.00	1,000.00
Gross Labour Cost (S\$)			2,110.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >