

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21010417/APS3Q2**Date:** 02/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993614
Claimant Vehicle No :	SKX6386R	Insured Vehicle No :	YP9506T
Date of Loss:	05/10/2021	Nature of Claim:	TP
		Claim No:	8654627327SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX6386R	Engine No:	CZC506002
Make & Model:	AUDI A3 SB, 1.4 TFSI AMBIENTE (A)	Chassis No:	WAUZZZ8VXGA074139
Reg. Date:	21/12/2015 (Man. Year: 2015)	Odometer:	32068 km
Colour:	Silver		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,132.00	4,459.76	4,672.24	51.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,902.00	2,292.00	2,610.00	53.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,034.00	6,751.76	7,282.24	51.89
+ GST 7.00/7.00% (S\$)	982.38	472.62	509.76	51.89
Nett Amount (S\$)	15,016.38	7,224.38	7,792.00	51.89
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,531.83		

INSPECTION

Date of Assignment:	13/10/2021		
Date Inspected:	13/10/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,016.00 FS	*1,612.80 FS
2	1		*RADIATOR GRILLE	Cut	691.00 FS	*552.40 FS
3	1		*RADIATOR GRILLE COVER	Not Necessary	98.00 FS	*- FS
4	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
5	1		*A/C STICKER	Necessary	8.00 FS	*5.68 FS
6	1		*BONNET	Dented	2,745.00 FS	*2,196.00 FS
7	1		*BONNET STRIKER	Not Necessary	110.00 FS	*- FS
8	1		*BONNET EDGE PROTECTION	Necessary	28.00 FS	*22.00 FS
9	1		*BONNET CATCH	Not Necessary	63.00 FS	*- FS
10	1		*BONNET LOCK	Not Necessary	214.00 FS	*- FS
11	1		*BONNET BOWDEN CABLE	Not Necessary	58.00 FS	*- FS
12	1		*BONNET BOWDEN CABLE COVER	Not Necessary	10.00 FS	*- FS
13	1		*FRONT BUMPER FORM PIECE	Not Necessary	83.00 FS	*- FS
14	1		*FRONT BUMPER REINFORCEMENT COVER	Not Necessary	56.00 FS	*- FS
15	1		*HEADLIGHT -RH	Not Necessary	2,641.00 FS	*- FS
16	2		*RADIATOR AIR GUIDE -UPPER CENTRE /RIGHT	Not Necessary	37.00 FS	*- FS
17	1		*AIR DUCT COVER (NPA)	Not Necessary	0.00 FS	*- FS
18	1		*AIR DUCT (NPA)	Not Necessary	0.00 FS	*- FS
19	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
20	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	9,132.00	4,459.76
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNES	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	250.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER BONNET AND RHS HEADLIGHT RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			4,902.00	2,292.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >