

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 958L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER REAR BUMPER	TO REPAIR SEE LABOUR	458.60	-
1	PANEL SUB-ASSY QUARTER LH	DEFORMED	836.70	836.70
10	BUMPER PIECE	NECESSARY	22.00	22.00
1	CAP WHEEL	SCRATCHED	177.70	177.70
1	FILLER-REAR BUMPER EXTENS	TO REPAIR SEE LABOUR	148.40	-
1	RETAINER RR BUMPER SIDE L	SERVICEABLE	112.70	-
	LESS 25% DISCOUNT		-439.03	-259.10
			1,317.07	777.30
	NETT ITEMS			
1	FUEL TANK LID (PETROL ONL)(N)	TO REPAIR SEE LABOUR	15.00	-
1	APP LOGO REAR DOOR L/R CC (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-9.50	-8.00
			85.50	72.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF COVER REAR BUMPER,FILLER-REAR BUMPER EXTENS AND FUEL TANK LID (PETROL ONL).		1,100.00	700.00
	SPRAYPAINT CHARGE.		800.00	750.00
	TUFF COAT ON AFFECTED PARTS.		50.00	20.00
	CHECK ALL LIGHTING.		50.00	20.00
	REMOVE/REFIX UPHOLSTERY REAR.		120.00	40.00
	RENEW ADVERTISEMENT STICKER-DOOR.		100.00	100.00
	RENEW ADVERTISEMENT STICKER-FENDER.		200.00	200.00
			2,420.00	1,830.00
	GRAND TOTAL		3,822.57	2,679.30





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,150.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC21010420/Vvy3n2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**