

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010425/T1ES3Q2**Date:** 05/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070176412
Claimant Vehicle No :	SHD3323H	Insured Vehicle No :	GBF6137U
Date of Loss:	08/10/2021	Nature of Claim:	TP
		Claim No:	5323020330SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3323H		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS081840
Reg. Date:	06/10/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU703569182
Colour:	Blue	Odometer:	465409 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,520.70	1,436.17	84.53	5.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	920.00	630.00	290.00	31.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,440.70	2,066.17	374.53	15.35
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	2,440.70	1,650.00	790.70	32.40
+ GST 7.00/7.00% (S\$)	170.85	115.50	55.35	32.40
Nett Amount (S\$)	2,611.55	1,765.50	846.05	32.40
+ Car Rental (4.0 x S\$125.40/day) (S\$)		501.60		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,269.10		

INSPECTION

Date of Assignment:	11/10/2021	
Date Inspected:	11/10/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	458.60 FL	*458.60 FL
2	1		*REAR BUMPER LOWER COVER	Deformed	552.60 FL	*552.60 FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	318.80 FL	*318.80 FL
4	1		*REAR BUMPER UNDER SIDE COVER RH	Deformed	232.60 FL	*232.60 FL
5	1		*REAR BUMPER TOW COVER	Deformed	82.70 FL	*82.70 FL
6	1		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	112.70 FL	*- FL
7	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
8	1		*BUMPER MAT	Necessary	50.00 FS	*50.00 FS
9	1		*BUMPER REVERSE SENSOR	Not Working	135.70 FS	*135.70 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	1,965.701,853.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	445.00416.83
					Total Parts (\$\$)	1,520.701,436.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	500.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	TUFF KOTE	New	60.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
Gross Labour Cost (\$\$)			920.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >