

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010426/KPA3Q2**Date:** 29/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070143955
Claimant Vehicle No :	SMN3145T	Insured Vehicle No :	GBK330R
Date of Loss:	11/10/2021	Nature of Claim:	TP
		Claim No:	3645425839SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN3145T	Engine No:	2ZR0D86155
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR800392451
Reg. Date:	31/07/2019 (Man. Year: 2019)	Odometer:	170971 km
Colour:	Metallic Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Rydanz 7 mm	Rear Left Side:	West Lake 9 mm
Front Right Side:	Rydanz 7 mm	Rear Right Side:	West Lake 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,682.35	1,461.92	1,220.43	45.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,390.00	910.00	480.00	34.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,072.35	2,371.92	1,700.43	41.76
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	4,072.35	1,900.00	2,172.35	53.34
+ GST 7.00/7.00% (S\$)	285.06	133.00	152.06	53.34
Nett Amount (S\$)	4,357.41	2,033.00	2,324.41	53.34
+ Loss of Use (5.0 x S\$103.00/day) (S\$)		515.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,550.00		
Global Sum Settlement (S\$)		2,450.00		

INSPECTION

Date of Assignment:	11/10/2021	City Auto Pte Ltd (Sin Ming) (HQ)
Date Inspected:	12/10/2021 Inspected At:	Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est
Estimated Period of Repair:	4.0 days	Singapore 575643

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,812.00 FL	*1,812.00 FL
2	1		*TAILGATE LOCK	Repair	712.70 FL	*- FL
3	1		*TAILGATE EMBLEM -HYBRID SYNERGY DRIVE	Necessary	58.90 FL	*58.90 FL
4	1		*REAR BUMPER	Repair	581.20 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
6	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
7	1		*REVERSE SENSOR	Serviceable	250.00 FS	*- FS
					Sub Total (\$\$)	3,479.80 1,935.90
					- List Item Discount on L Items 25.00/25.00% (\$\$)	797.45 473.98
					Total Parts (\$\$)	2,682.35 1,461.92

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS	New	150.00	120.00
2	TO INSTALL REVERSE SENSOR	New	40.00	40.00
3	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS	New	600.00	350.00
4	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	600.00	400.00
Gross Labour Cost (\$\$)			1,390.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >