

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004056/BRA3Q2-1
Date: 25/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0100647915	
Claimant Vehicle No :	SLE5298G	Insured Vehicle No :	SGH6054E	
Date of Loss:	14/03/2020	Nature of Claim:	TP	Claim No: 0352411205SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE5298G		
Make & Model:	HONDA VEZEL, 1.5 S (A)	Engine No:	L15B4027364
Reg. Date:	26/07/2016 (Man. Year: 2015)	Chassis No:	RU11107359
Colour:	White	Odometer:	100550 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,508.88	22,142.46	14,366.42	39.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,960.00	4,270.00	2,690.00	38.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,468.88	26,412.46	17,056.42	39.24
Approved Total (Overridden) (S\$)		21,000.00		

Nett Amount (S\$)	43,468.88	21,000.00	22,468.88	51.69
+ Car Rental (12.0 x S\$80.00/day) (S\$)		960.00		
(S\$)		21,960.00		
Liabe Amount (80.00%) (S\$)		17,568.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		90.00		
Nett Liability (S\$)		17,665.45		
Global Sum Settlement (S\$)		17,500.00		

INSPECTION

Date of Assignment: 16/03/2020

Date Inspected: 16/03/2020

Estimated Period of Repair: 12.0 days

Inspected At:

Team AutoPro Pte Ltd - Sin Ming (HQ)
 160 Sin Ming Drive #01-14 Sin Ming Autocity
 Singapore 575722

Adjuster: Lim Teow Guan**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,050.00 FL	*880.00 FL
2	1		*FRONT BUMPER LOWER	Broken	485.60 FL	*389.20 FL
3	1		*FRONT BUMPER CENTRE GRILLE	Broken	198.60 FL	*198.60 FL
4	2		*FRONT BUMPER FOG LAMP	Broken	913.40 FL	*913.40 FL
5	1		*FRONT BUMPER FOG LAMP GARNISH	O/S Dislodged	252.40 FL	*126.20 FL
6	1		*FRONT BUMPER TOW CAP	Not Damaged	83.20 FL	*- FL
7	1		*FRONT GRILLE	Broken	582.30 FL	*345.00 FL
8	1		*FRONT GRILLE LOGO	Missing	89.00 FL	*58.00 FL
9	1		*FRONT GRILLE BASE	Broken	413.60 FL	*374.20 FL
10	1		*FRONT GRILLE OUTER CHROME GARNISH	Broken	368.00 FL	*368.00 FL
11	2		*FRONT GRILLE TOP BRACKET SIDE	Broken	174.60 FL	*174.60 FL
12	1		*FRONT GRILLE TOP BRACKET CENTRE	Bent	198.00 FL	*198.00 FL
13	1		*FRONT LICENSE PLATE	Bent	98.00 FL	*50.00 FL
14	1		*FRONT BUMPER REINFORCEMENT	Bent	486.00 FL	*486.00 FL
15	2		*FRONT BUMPER SIDE RETAINER	Necessary	144.00 FL	*120.00 FL
16	2		*HEADLAMP ASSY	Broken	4,291.80 FL	*3,569.00 FL
17	2		*HEADLAMP BRACKET	Broken	152.00 FL	*152.00 FL
18	1		*BONNET	Dented	1,034.70 FL	*950.40 FL
19	1		*BONNET LOCK ASSY	Jammed	234.60 FL	*135.50 FL
20	1		*BONNET INSULATOR	No such part	396.40 FL	*- FL
21	2		*BONNET HINGE	Bent	178.00 FL	*178.00 FL
22	2		*BONNET RUBBER (SHORT)	Not Necessary	182.00 FL	*- FL
23	1		*BONNET RUBBER (LONG)	Not Necessary	135.00 FL	*- FL
24	1		*WINDSCREEN	Broken	1,800.00 FL	*1,345.10 FL
25	2		*WINDSCREEN MOULDING	Necessary	519.60 FL	*284.00 FL
26	1		*FRONT SUPPORT PANEL	Bent	898.00 FL	*374.50 FL
27	1		*FRONT SUPPORT TOP PANEL GARNISH	Dislodged	185.00 FL	*185.00 FL
28	1		*FRONT FENDER LH	Repair	756.00 FL	*- FL
29	1		*FRONT FENDER RH	Repair	756.00 FL	*- FL
30	1		*FRONT FENDER INNER SHIELD LH	Not Damaged	134.20 FL	*- FL
31	1		*FRONT FENDER INNER SHIELD RH	Not Damaged	134.20 FL	*- FL
32	2		*FRONT FENDER ARCH GARNISH	Dislodged	257.80 FL	*257.80 FL
33	1		*FRONT WIPER TANK	Bent	265.80 FL	*265.80 FL
34	1		*FRONT DRIER AIR BAG	Dislodged	2,980.00 FL	*1,840.30 FL
35	1		*DASHBOARD	Broken	2,548.20 FL	*2,236.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*DASHBOARD AIR BAG	Dislodged	2,863.70 FL	*1,640.30 FL
37	2		*AIRBAG SENSOR	Activated	636.00 FL	*180.00 FL
38	1		*AIRBAG ECU MODULE	Not Necessary	2,658.10 FL	*- FL
39	2		*FRONT SAFETY BELT	Jammed	1,621.00 FL	*1,400.60 FL
40	1		*STEERING AIRBAG COIL	Not Necessary	654.20 FL	*- FL
41	2		*FRONT SAFETY BELT KNUCKLE	Not Damaged	336.00 FL	*- FL
42	1		*RADIATOR	Broken	987.90 FL	*987.90 FL
43	2		*RADIATOR FAN MOTOR	Broken	1,076.00 FL	*916.80 FL
44	2		*RADIATOR FAN COWLING	Broken	431.20 FL	*250.00 FL
45	2		*RADIATOR FAN BLADE	Broken	232.00 FL	*232.00 FL
46	1		*RADIATOR TOP HOSE	Necessary	148.60 FL	*57.30 FL
47	1		*RADIATOR LOWER HOSE	Necessary	159.30 FL	*57.38 FL
48	1		*FAN BELT	Not Necessary	194.50 FL	*- FL
49	1		*AIRCON COMPRESSER	Not Damaged	853.20 FL	*- FL
50	1		*AIRCON COMPRESSER BELT	Necessary	354.00 FL	*80.00 FL
51	1		*AIRCON CONDENSER	Broken	985.00 FL	*868.10 FL
52	1		*AIRCON SUCTION HOSE	Bent	398.00 FL	*150.00 FL
53	1		*AIRCON DISCHARGE HOSE	Bent	352.00 FL	*150.00 FL
54	1		*AIR DUCT	Broken	86.90 FL	*77.50 FL
55	1		*AIR CLEANER BOX	Not Damaged	482.10 FL	*- FL
56	1		*FRONT CHASSIS MEMBER (RH)	Bent	1,985.60 FL	*1,510.00 FL
57	1		*ALTORNATER ASSY	Broken	985.20 FL	*985.20 FL
58	1		*STARTER MOTOR ASSY	Bent	954.60 FL	*954.60 FL
59	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
60	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
61	1		*FRONT BUMPER LOWER CLIPS	Necessary	50.00 FS	*30.00 FS
62	1		*FRONT BUMPER CENTRE GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
63	2		*FRONT BUMPER FOG LAMP GARNISH CLIPS	No such part	100.00 FS	*- FS
64	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
65	1		*BONNET SEALANT	Not Necessary	80.00 FS	*- FS
66	1		*BONNET INSULATOR CLIPS	No such part	50.00 FS	*- FS
67	3		*BONNET RUBBER CLIPS	Not Necessary	150.00 FS	*- FS
68	1		*FRONT FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
69	1		*NUMBER PLATE WITH CASING	Bent	80.00 FS	*50.00 FS
70	1		*FRONT WINDSCREEN CLIPS	Necessary	50.00 FS	*30.00 FS
71	1		*FRONT WINDSCREEN PRIMER AND CLEANER	Not Necessary	100.00 FS	*- FS
72	1		*FRONT WINDSCREEN SEALANT	Necessary	100.00 FS	*50.00 FS
73	1		*FRONT WINDSCREEN INNER SEAL	Necessary	80.00 FS	*30.00 FS
74	1		*FRONT SUPPORT PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
75	1		*FRONT WINDSCREEN TINTED	Not Necessary	180.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
76	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
77	2		*FRONT FENDER SEALANT	Not Necessary	160.00 FS	*- FS
78	2		*FRONT FENDER ARCH GARNISH CLIPS	Necessary	100.00 FS	*50.00 FS
79	2		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	100.00 FS	*- FS
80	1		*ERP BRACKET	Necessary	80.00 FS	*40.00 FS
81	1		*HORN	Cracked	150.00 FS	*50.00 FS
82	1		*RADIATOR FLUID	Necessary	60.00 FS	*30.00 FS
83	1		*AIRCON FLUID	Necessary	100.00 FS	*40.00 FS
84	1		*RADIATOR COOLANT	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	45,071.10	27,533.08
- List Item Discount on L Items 20.00/20.00% (\$)	8,562.22	5,390.62
Total Parts (\$)	36,508.88	22,142.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	2,000.00	1,600.00
2	SPRAY PAINTING	New	1,800.00	1,000.00
3	RUST PROOFING	New	100.00	40.00
4	R&R WIPER PANEL	New	150.00	50.00
5	R&R ABS PUMP	New	250.00	100.00
6	CHECK WIRING /BULB	New	80.00	50.00
7	R&R RADIATOR	New	150.00	80.00
8	R&R CONDENSER	New	150.00	80.00
9	R&R AIRCON COMPRESSOR	New	150.00	80.00
10	R&R ALTERNATOR ASSY	New	150.00	80.00
11	R&R STARTER MOTOR ASSY	New	150.00	80.00
12	DIAGNOSTIC AND RESET FAULT CODE	New	300.00	120.00
13	R&R AIR BAG	New	200.00	80.00
14	R&R WINDSCREEN FRONT	New	200.00	100.00
15	UPHOLSTERY	New	200.00	80.00
16	R&R ECU SYSTEM	New	80.00	40.00
17	MOUNT WORK BENCH	New	200.00	200.00
18	WHEEL ALIGNMENT	New	150.00	60.00
19	CHASSIS ALIGNMENT	New	200.00	200.00
20	R&R DASHBOARD	New	300.00	150.00
Gross Labour Cost (S\$)			6,960.00	4,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >