

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21010429/EES3Q2  
**Date:** 05/01/2022**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
<b>Claimant Vehicle No :</b>	SMX2022T	<b>Insured Vehicle No :</b>	SLW8172X
Date of Loss:	26/09/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004171

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMX2022T</b>		
Make & Model:	BMW 216I, 1.5 (A)	Engine No:	34015253B38A15A
Reg. Date:	15/08/2018 (Man. Year: 2018)	Chassis No:	WBA2D920805K81141
Colour:	Blue	Odometer:	42673 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,623.60	3,507.45	1,116.15	24.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,656.00	5,127.00	1,529.00	22.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,279.60</b>	<b>8,634.45</b>	<b>2,645.15</b>	<b>23.45</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>789.57</b>	<b>604.41</b>	<b>185.16</b>	<b>23.45</b>

<b>Nett Amount (S\$)</b>	<b>12,069.17</b>	<b>9,238.86</b>	<b>2,830.31</b>	<b>23.45</b>
		<b>+ Loss of Use (5.0 x S\$60.00/day) (S\$)</b>	300.00	
		<b>+ Doc/Search Fee (S\$)</b>	7.45	
		<b>Nett Liability (S\$)</b>	<b>9,546.31</b>	

INSPECTION

Date of Assignment: 11/10/2021

Date Inspected: 12/10/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Performance Motors Limited (Alexandra)  
 303 Alexandra Road, Sime Darby Performance Centre  
 Singapore 159941

**Adjuster:** CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2021)
<b>Parts:</b>	M1-MPV	BMW 216I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMX2022T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*BOOTLID	Dented	1,216.40 FS	*1,216.40 FS
3	1		*REAR BUMPER CARRIER	Dented	483.40 FS	*483.40 FS
4	1		*SUPPORT	Not Necessary	45.75 FS	*- FS
5	1		*RR BUMPER LH INNER SIDE GUIDE	Not Necessary	161.15 FS	*- FS
6	1		*RR BUMPER RH INNER SIDE GUIDE	Not Necessary	161.15 FS	*- FS
7	1		*REAR BUMPER TRIM STRIP (CHROM)	Cut	110.55 FS	*110.55 FS
8	1		*REAR BUMPER PANEL PRIMED (LI)	Dented	1,050.65 FS	*1,050.65 FS
9	1		*LETTERING 216I	Necessary	64.75 FS	*64.75 FS
10	2		*GROMMET	Necessary	1.60 FS	*1.60 FS
11	1		*PLAQUE 74MM	Necessary	71.95 FS	*71.95 FS
12	1		*REAR WINDOW ESG	Not Necessary	657.60 FS	*- FS
13	6		*HOOK AND LOOP FASTENER	Not Necessary	13.20 FS	*- FS
14	1		*REAR BUMPER HEAT INSULATION	Not Necessary	77.30 FS	*- FS
15	1		*REAR LH REFLECTOR	Missing	39.05 FS	*39.05 FS
16	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
17	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
18	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Necessary	27.85 FS	*27.85 FS
19	2		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** **4,623.60** **3,507.45**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER ,BOOT LID INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	2,550.00	1,700.00
2	TO RESPRAY REAR BUMPER AND BOOT LID	New	1,923.00	1,826.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	112.00
4	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR	New	574.00	574.00
5	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
6	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
7	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECK ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	504.00
8	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
9	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,656.00</b>	<b>5,127.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >