



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN			Ref: CC4/ASM21010437/Ara3q2 Date: 18/02/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 3211C	Veh. Inspected	GBK 7128M
	Policy No.	P2419138	Coverage (\$)	0.00
	Claim No.	S1M03JRF	Excess (\$)	0.00
	Assign From		Assign Date	11/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	JTFHT02P200250724	Colour	SILVER
	Odometer	34948 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm
	L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm
	R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm
	L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/10/2021	Inspection Date	12/10/2021
	Survey held at	SIN FATT DIESEL MOTOR COMPANY BLK 3020A UBI ROAD 1 #01-38 . SINGAPORE 408714		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	