

SIN FATT DIESEL MOTOR

BLOCK 3020A UBI ROAD 1 #01-33 SINGAPORE 408714

DCSDRIVER ENGINEERING & TRADING
BLOCK 3020A UBI ROAD 1
01-33
Singapore 408714

12th OCT 2021

TP AKA.

Juslin.

JT FHT02 P200250784

Accident date: 09.10.21

Estimated repair cost for vehicle no: GBK7128M TOYOTA HIACE ' 2010 (COE TIL 2030)

S/n	Qty	Items	U/price	Amount
1	1	Rear boot lid <i>Dented</i>		\$2,500.00 1755.
2	1	Rear boot lid HIACE logo		\$74.40 35
3	1	Rear boot lid Emble logo		\$61.00 ✓
4	1	Rear boot lid 70Km/h logo		\$20.00 ✓
5	1	Rear boot lid body logo		\$850.00 400(SN)
6	1	Rear boot lid center moulding <i>new</i>		\$258.00 x
7	1	Rear boot lid inner lock <i>Dented</i>		\$385.20 287.
8	1	Rear boot lid inner trim board <i>new</i>		\$550.00 +
9	10	Rear boot lid inner clips	\$12.90	\$129.00 +
10	1	Rear boot lid inner rubber <i>new</i>		\$329.10 -
11	2	Rear boot lid number plate lamp <i>new</i>	\$83.20	\$166.40 +
12	1	Rear boot lid number plate		\$50.00 +
13	2	Rear tail lamp <i>RH cracked</i>	\$425.00	\$850.00 345
14	2	Rear tail lamp lower panel <i>new</i>	\$252.20	\$504.40 x
15	2	Rear tail lamp lower panel bracket <i>new</i>	\$131.75	\$263.50 +
16	2	tail lamp lower cover <i>RH Deformed</i>	\$121.20	\$242.40 121.20
17	1	tail lamp panel- RH <i>Dented</i>		\$822.00 485
18	1	Rear bumper <i>Deformed</i>		\$825.20 496.
19	2	Rear bumper side bracket <i>new</i>	\$215.20	\$430.40 64.
20	1	Rear bumper reverse sensor <i>Damaged</i>		\$350.00 200(SN)
21	1	rear bumper rear camera <i>new</i>		\$450.00 x
22	6	Rear bumper clips <i>new</i>	\$12.90	\$77.40 30.
23	1	Rear end panel <i>Distorted</i>		\$925.20 581
24	1	end panel top garnish <i>new</i>		\$315.20 x
25	1	Rear spare tire bracket <i>new</i>		\$358.20 x
26	1	rear fender -RH <i>new</i>		\$2,250.00 x
27	1	rear fender body logo -RH <i>new</i>		\$1,050.00 480(SN)
28	1	air duct <i>Deformed</i>		\$85.00 ✓
29	1	Rear exhaust <i>new</i>		\$985.00 x

4365.20

Subtotal :- \$16,156.70

3273.90 S/N: 1080.

Labour charges

To remove & re-fix rear windscreen

\$120.00 ✓

Gum

\$50.00 ✓

To remove & re-fix rear reverse sensor

~~\$120.00~~ 50

To remove & re-fix rear exhaust

\$180.00 X

To remove & re-fix rear cushion

~~\$120.00~~ 60

To check wiring system

~~\$60.00~~ 30

Panel beating

~~\$1,500.00~~ 11200

Spray painting

~~\$1,500.00~~ 1200

To remove and re-fix rear camera.

50
100
280
300

Subtotal :-

\$3,650.00

To remove and re-fix internal furniture

120
200

Total:-

\$19,806.70

To spray tuft coat

total: 7513.90

4/5: 6K

OT Days.

6K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: