

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21010439/BPA3Q2**Date:** 11/08/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_01

Claimant Vehicle No : SMW4949L **Insured Vehicle No :** GBK6752S

Date of Loss: 08/10/2021 Nature of Claim: TP Claim No: MFL2021D0004436

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMW4949L**

Make & Model: NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) Engine No: HR16944595B

Reg. Date: 18/07/2014 (Man. Year: 2014) Chassis No: MNTBBAB17Z0019258

Colour: Silver Odometer: 90817 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,140.68	3,878.51	4,262.17	52.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,050.00	1,540.00	2,510.00	61.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,190.68	5,418.51	6,772.17	55.55
Approved Total (Overridden) (S\$)		4,100.00		
(S\$)	12,190.68	4,100.00	8,090.68	66.37
+ GST 7.00/7.00% (S\$)	853.35	287.00	566.35	66.37
Nett Amount (S\$)	13,044.03	4,387.00	8,657.03	66.37
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,874.45		
Global Sum Settlement (S\$)		4,850.00		

INSPECTION

Date of Assignment: 11/10/2021

Date Inspected: 12/10/2021 Inspected At:

Estimated Period of Repair: 6.0 days

Team Autopro Pte Ltd (sin Ming) (HQ)
 160 SIN MING DRIVE, #01-14 SIN MING
 AUTOCITY
 Singapore 575722

8/11/22, 9:13 AM

Adjuster Report

Adjuster: Lim Teow Guan

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Nov 2021)

Parts: 143 NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMW4949L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,250.10 FL	*798.00 FL
2	1		*BOOTLID LOGO	Necessary	108.90 FL	*45.00 FL
3	1		*BOOTLID EMBLEM SYLPHY	Necessary	118.60 FL	*42.00 FL
4	1		*BOOTLID EMBLEM XTRONIC CVT	Necessary	84.90 FL	*45.60 FL
5	2		*BOOTLID LAMP	Broken	891.00 FL	*483.20 FL
6	1		*BOOTLID OUTER CHROME GARNISH	Broken	258.00 FL	*158.00 FL
7	1		*BOOTLID OUTER CHROME LOWER GARNISH	Cut	125.30 FL	*125.30 FL
8	1		*BOOTLID INNER TRIM BOARD	Not Damaged	198.30 FL	*- FL
9	1		*BOOTLID WEATHERSTRIP	Torn	286.30 FL	*91.10 FL
10	1		*BOOTLID LOCK	Jammed	107.90 FL	*107.90 FL
11	1		*REAR BUMPER	Dented	879.90 FL	*518.80 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	174.80 FL	*72.60 FL
13	1		*REAR BUMPER INNER SPONGE CENTRE	Broken	68.30 FL	*68.30 FL
14	2		*REAR BUMPER INNER SPONGE SIDE	No such part	303.68 FL	*- FL
15	2		*REAR BUMPER REINFORCEMENT STOPPER	Not Damaged	105.60 FL	*- FL
16	2		*REAR BUMPER REFLECTOR	Not Damaged	151.80 FL	*- FL
17	1		*REAR END PANEL	Dented	783.60 FL	*454.30 FL
18	1		*REAR END PANEL TOP GARNISH	Not Damaged	108.40 FL	*- FL
19	2		*TAILLAMP	Broken	1,317.60 FL	*943.80 FL
20	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
21	1		*BOOTLID SEALANT	Necessary	100.00 FS	*30.00 FS
22	2		*BOOTLID LAMP SEAL	No such part	120.00 FS	*- FS
23	2		*BOOTLID LAMP CLIPS	Necessary	100.00 FS	*20.00 FS
24	1		*BOOTLID OUTER CHROME GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
25	1		*BOOTLID OUTER CHROME LOWER GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
26	1		*BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
27	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
28	2		*REAR BUMPER REVERSE SENSOR	Scratched	500.00 FS	*200.00 FS
29	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
30	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
31	2		*TAILLAMP CLIPS	No such part	100.00 FS	*- FS
32	2		*TAILLAMP SEAL	No such part	120.00 FS	*- FS
33	1		*REAR NUMBER PLATE W/CASING	Not Damaged	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,872.98	4,273.90
- List Item Discount on L Items 10.00/10.00% (\$\$)	732.30	395.39
Total Parts (\$\$)	8,140.68	3,878.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BOOTLID COMPONENT	New	150.00	80.00
2	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
3	UPHOLSTERY	New	300.00	0.00
4	CHECK WIRING	New	100.00	0.00
5	PANEL BEATING	New	1,600.00	800.00
6	RUST PROOFING	New	200.00	0.00
7	SPRAY PAINTING	New	1,600.00	600.00
Gross Labour Cost (\$\$)			4,050.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >