

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21010440/UGA3Q2
Date: 05/01/2022

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700022616
Claimant Vehicle No : SMK8589D **Insured Vehicle No :** SLQ6606G
Date of Loss: 08/10/2021 Nature of Claim: TP Claim No: 6351747392SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK8589D**
Make & Model: HONDA SHUTTLE, 1.5 G CVT (A) Engine No: L15B6001514
Reg. Date: 26/04/2019 (Man. Year: 2018) Chassis No: GK82001222
Colour: Grey Odometer: 97744 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16
Front Left Side: Falken 7 mm Rear Left Side: Falken 7 mm
Front Right Side: Falken 7 mm Rear Right Side: Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,567.25	1,477.50	1,089.75	42.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	1,220.00	860.00	41.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,647.25	2,697.50	1,949.75	41.95
+ GST 7.00/7.00% (S\$)	325.31	188.83	136.48	41.95
Nett Amount (S\$)	4,972.56	2,886.33	2,086.23	41.95
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,388.33		
Global Sum Settlement (S\$)		3,380.00		

INSPECTION

Date of Assignment: 14/10/2021
Date Inspected: 14/10/2021 Inspected At: Hock Wah Motor Workshop Pte Ltd (Bedok)
Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
Singapore 489977
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE (WCP)	Badly Dented	585.00 F	*585.00 F
2	1		*REAR BUMPER (WCP)	Dented / Deformed	530.00 F	*530.00 F
3	4		*REAR BUMPER CLIP (WCP)	Not Necessary	12.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT (WCP) (NPA)	No such part	0.00 F	*- F
5	1		*END PANEL (WCP)	Repair	300.00 F	*- F
6	1		*TAILGATE LOCK (WCP)	Not Necessary	75.00 F	*- F
7	1		*TAILGATE LOGO -SHUTTLE (WCP)	Necessary	40.00 F	*35.00 F
8	1		*TAILGATE EMBLEM (WCP)	Not Necessary	18.00 F	*- F
9	1		*TAILGATE CHROME (WCP)	Not Necessary	235.00 F	*- F
10	1		*TAILGATE WINDSCREEN MOULDING (WCP) (NPA)	Necessary	0.00 F	*- F
11	1		*REAR BUMPER INNER SPONGE LH (WCP)	Torn	40.00 F	*40.00 F
12	1		*TAILGATE WINDSCREEN MOULDING TOP (WCP)	Necessary	20.00 F	*20.00 F
13	1		*TAILGATE WINDSCREEN MOULDING BOTTOM (WCP)	Necessary	40.00 F	*40.00 F
14	1		*REVERSE SENSOR	Serviceable	280.00 FS	*- FS
15	1		*REAR NUMBER PLATE	Serviceable	30.00 FS	*- FS
16	1		*REAR NUMBER PLATE HOLDER	Serviceable	30.00 FS	*- FS
17	2		*REAR WINDSCREEN SEALANT	Necessary	48.00 FS	*40.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	2,283.00	1,290.00
+ Margin on L,N Items 15.00/15.00% (S\$)	284.25	187.50
Total Parts (S\$)	2,567.25	1,477.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	800.00	450.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	580.00
3	ANTI-RUST COATING	New	150.00	30.00
4	TO REMOVE & REFIT WINDSCREEN	New	180.00	120.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	40.00
			Gross Labour Cost (\$)	2,080.00
				1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >