

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21010441/TGA3Q2**Date:** 16/06/2022REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2070164866   |
| <b>Claimant Vehicle No :</b> | SH6959C                              | <b>Insured Vehicle No :</b> | YP4983G      |
| Date of Loss:                | 09/10/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 2202584008SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                      |             |                   |
|-----------------------------|--------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SH6959C</b>                       | Engine No:  | G4LEKU429717      |
| Make & Model:               | HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A) | Chassis No: | KMHC851CVLU194735 |
| Reg. Date:                  | 28/09/2021 (Man. Year: 2019)         | Odometer:   | 4581 km           |
| Colour:                     | Blue                                 |             |                   |
| Engine Capacity:            | 1580 cc                              |             |                   |
| Market Value/New Car Price: | N/A                                  |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>    |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |                |                  |                |
|-------------------|----------------|------------------|----------------|
| Front Tyre Size:  | 195/65 R15     | Rear Tyre Size:  | 195/65 R15     |
| Front Left Side:  | West Lake 6 mm | Rear Left Side:  | West Lake 6 mm |
| Front Right Side: | West Lake 6 mm | Rear Right Side: | West Lake 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 7,739.84          | 5,618.64          | 2,121.20          | 27.41         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 2,110.00          | 1,400.00          | 710.00            | 33.65         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>                        | <b>9,849.84</b>   | <b>7,018.64</b>   | <b>2,831.20</b>   | <b>28.74</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 689.49            | 491.30            | 198.19            | 28.74         |
| <b>Nett Amount (S\$)</b>                        | <b>10,539.33</b>  | <b>7,509.94</b>   | <b>3,029.39</b>   | <b>28.74</b>  |
| <b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b> |                   | 200.00            |                   |               |
| <b>+ Car Rental (4.0 x S\$125.19/day) (S\$)</b> |                   | 500.76            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 2.00              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>8,212.70</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>8,200.00</b>   |                   |               |

INSPECTION

|                             |            |                                                                                                 |
|-----------------------------|------------|-------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 11/10/2021 |                                                                                                 |
| Date Inspected:             | 11/10/2021 | Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)<br>59 Loyang Drive<br>Singapore 508969 |
| Estimated Period of Repair: | 3.0 days   |                                                                                                 |

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *REAR BUMPER COVER                    | Cracked       | 459.40 FL   | *459.40 FL   |
| 2   | 10  |          | *REAR BUMPER CLIPS                    | Necessary     | 22.00 FL    | *22.00 FL    |
| 3   | 1   |          | *REAR BUMPER CENTRE MOULDING ASSY     | Deformed      | 451.25 FL   | *451.25 FL   |
| 4   | 1   |          | *REAR BUMPER REINFORCEMENT            | Not Necessary | 394.80 FL   | *- FL        |
| 5   | 1   |          | *REAR BUMPER REINFORCEMENT BRACKET LH | Not Necessary | 138.10 FL   | *- FL        |
| 6   | 1   |          | *REAR BUMPER TOWING COVER             | Cut           | 98.80 FL    | *98.80 FL    |
| 7   | 1   |          | *REAR BUMPER REFLECTOR LAMP LH        | Cut           | 41.45 FL    | *41.45 FL    |
| 8   | 1   |          | *ANTENNA ASSY SMARTKEY                | Not Necessary | 40.50 FL    | *- FL        |
| 9   | 1   |          | *REAR PANEL                           | Repair        | 532.00 FL   | *- FL        |
| 10  | 1   |          | *REAR PANEL GARNISH                   | Not Necessary | 346.80 FL   | *- FL        |
| 11  | 1   |          | *BOOTLID LAMP LH                      | Cracked       | 794.40 FL   | *794.40 FL   |
| 12  | 1   |          | *BOOTLID                              | Bent          | 2,480.40 FL | *2,480.40 FL |
| 13  | 1   |          | *BOOTLID HYUNDAI PLATE                | Necessary     | 24.30 FL    | *24.30 FL    |
| 14  | 1   |          | *EMBLEM HYBRID                        | Necessary     | 24.30 FL    | *24.30 FL    |
| 15  | 1   |          | *EMBLEM -IONIQ                        | Necessary     | 31.30 FL    | *31.30 FL    |
| 16  | 1   |          | *BOOT LID GLASS LOWER                 | Broken        | 584.90 FL   | *584.90 FL   |
| 17  | 1   |          | *BOOT LID GLASS LOWER MOULDING        | Not Necessary | 145.20 FL   | *- FL        |
| 18  | 1   |          | *REAR SPOILER                         | Cracked       | 665.40 FL   | *665.40 FL   |
| 19  | 1   |          | *TAIL LAMP LH                         | Cut           | 870.40 FL   | *870.40 FL   |
| 20  | 1   |          | *BOOT LID LAMP LH                     | Not Necessary | 794.40 FL   | *- FL        |
| 21  | 1   |          | *BOOTLID TRIMBOARD                    | Not Necessary | 259.70 FL   | *- FL        |
| 22  | 1   |          | *REAR BUMPER RUBBER MAT               | Necessary     | 50.00 FS    | *50.00 FS    |
| 23  | 1   |          | *BOOTLID COMFORT TEL NO STICKER       | Necessary     | 35.00 FS    | *35.00 FS    |
| 24  | 1   |          | *BOOTLID COMFORT LOGO STICKER         | Necessary     | 30.00 FS    | *30.00 FS    |
| 25  | 1   |          | *BOOTLID COMFORT APP STICKER          | Necessary     | 30.00 FS    | *30.00 FS    |
| 26  | 1   |          | *REAR BUMPER REVERSE SENSOR           | Necessary     | 180.00 FS   | *180.00 FS   |
| 27  | 1   |          | *REAR NUMBER PLATE                    | Cracked       | 55.00 FS    | *55.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>9,579.80</b> | <b>6,928.30</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | 1,839.96        | 1,309.66        |
| <b>Total Parts (\$\$)</b>                                  | <b>7,739.84</b> | <b>5,618.64</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars                 | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-----------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                             |          |                 |                 |
| 1                               | PANEL BEATING               | New      | 1,100.00        | 750.00          |
| 2                               | SPRAY PAINTING CHARGE       | New      | 750.00          | 500.00          |
| 3                               | CHK ALL LIGHTING            | New      | 60.00           | 30.00           |
| 4                               | TUFF KOTE                   | New      | 60.00           | 30.00           |
| 5                               | REMOVE/REFIX REVERSE SENSOR | New      | 80.00           | 30.00           |
| 6                               | TOWING FEE                  | New      | 60.00           | 60.00           |
| <b>Gross Labour Cost (\$\$)</b> |                             |          | <b>2,110.00</b> | <b>1,400.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >