

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010442/BPA3Q2**Date:** 29/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070062887
Claimant Vehicle No :	YQ3625S	Insured Vehicle No :	GBF9659K
Date of Loss:	08/10/2021	Nature of Claim:	TP
		Claim No:	0917939207SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ3625S	Engine No:	4HK10GX242
Make & Model:	ISUZU NPR75UH5A, 5.2 D (M)	Chassis No:	JAANPR75HM7100399
Reg. Date:	23/04/2021 (Man. Year: 2021)	Odometer:	8042 km
Colour:	White		
Engine Capacity:	5193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/75 R17.5	Rear Tyre Size:	215/75 R17.5
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,898.19	12,930.34	25,967.85	66.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,950.00	4,180.00	7,770.00	65.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	50,848.19	17,110.34	33,737.85	66.35
Approved Total (Overridden) (S\$)		13,650.00		
(S\$)	50,848.19	13,650.00	37,198.19	73.16
+ GST 7.00/7.00% (S\$)	3,559.37	955.50	2,603.87	73.16
Nett Amount (S\$)	54,407.56	14,605.50	39,802.06	73.16
+ Loss of Use (18.0 x S\$120.00/day) (S\$)		2,160.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		1,800.00		
Nett Liability (S\$)		18,572.95		

INSPECTION

Date of Assignment:	11/10/2021	Team Autopro Pte Ltd (sin Ming) (HQ)
Date Inspected:	12/10/2021 Inspected At:	160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
Estimated Period of Repair:	15.0 days	Singapore 575722

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT CORNER GARNISH RH	Dented	458.50 FL	*212.00 FL
2	1		*FRONT BUMPER	Dented	728.00 FL	*575.00 FL
3	2		*FRONT BUMPER BRACKET	Not Damaged	409.20 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP RH	Not Damaged	384.00 FL	*- FL
5	1		*FRONT DOOR RH	Dented	1,278.00 FL	*1,120.00 FL
6	1		*FRONT DOOR SIGNAL LAMP RH	Broken	175.80 FL	*117.00 FL
7	1		*FRONT DOOR WEATHERSTRIP	Not Damaged	245.60 FL	*- FL
8	1		*FRONT DOOR INNER RUBBER RH	Not Damaged	289.00 FL	*- FL
9	1		*FRONT DOOR HANDLE RH	Cut	472.60 FL	*215.00 FL
10	1		*FRONT DOOR OUTER MOULDING RH	Cut	346.60 FL	*165.90 FL
11	2		*FRONT DOOR HINGE	Not Damaged	372.00 FL	*- FL
12	1		*FRONT DOOR PILLAR OUTER	Dented	985.30 FL	*688.10 FL
13	1		*FRONT DOOR GLASS RH	Cut	855.00 FL	*488.00 FL
14	1		*FRONT DOOR GLASS CHANNEL RH	Not Damaged	148.70 FL	*- FL
15	1		*FRONT DOOR REGULATOR RH	Not Damaged	651.00 FL	*- FL
16	1		*FRONT DOOR REGULATOR MOTOR RH	Not Damaged	395.60 FL	*- FL
17	1		*FRONT STEP GARNISH RH	Dented	298.70 FL	*172.00 FL
18	1		*FRONT STEP GARNISH REFLECTOR RH	Necessary	87.00 FL	*24.40 FL
19	1		*FRONT CHROME GRILLE	Not Damaged	550.00 FL	*- FL
20	1		*WING MIRROR RH	Broken	167.00 FL	*167.00 FL
21	1		*WING MIRROR ARM BRACKET RH	Bracket torn	498.60 FL	*287.00 FL
22	1		*WING MIRROR COVER RH	Missing	87.20 FL	*87.20 FL
23	1		*WINDSCREEN	Not Damaged	1,985.30 FL	*- FL
24	1		*FRONT WINDSCREEN RUBBER UPPER	Cut	387.20 FL	*299.00 FL
25	1		*FRONT WINDSCREEN RUBBER LOWER	Not Damaged	210.00 FL	*- FL
26	1		*HEADLAMP RH	Broken	560.00 FL	*306.00 FL
27	1		*HEADLAMP UPPER GARNIS RH	Not Damaged	184.00 FL	*- FL
28	1		*SIGNAL LAMP RH	Repeated	280.00 FL	*- FL
29	1		*AIR FILTER HOUSING	No such part	853.60 FL	*- FL
30	1		*MUDFLAP RH	No such part	443.80 FL	*- FL
31	1		*FRONT SHOCK ABSORBER	O/S Bent	1,463.12 FL	*528.70 FL
32	1		*FRONT WHEEL HUB	O/S Dented	4,292.92 FL	*760.00 FL
33	1		*FRONT WHEEL HUB BEARING	O/S Jammed	1,189.60 FL	*175.00 FL
34	1		*FRONT WHEEL ARM (TOP)	O/S Necessary	2,853.42 FL	*516.20 FL
35	1		*FRONT WHEEL ARM (LOWER)	O/S Necessary	3,899.02 FL	*652.20 FL
36	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
37	1		*FRONT CORNER GARNISH CLIPS	Necessary	100.00 FS	*30.00 FS
38	1		*FRONT DOOR SEALANT	Necessary	100.00 FS	*20.00 FS
39	1		*FRONT DOOR PILLAR OUTER SEALANT	Necessary	100.00 FS	*20.00 FS
40	1		*FRONT WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
41	1		*FRONT WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
42	1		*FRONT WINDSCREEN PRIMER & CLEANER	Not Necessary	80.00 FS	*- FS
43	1		*FRONT STEP GARNISH CLIPS	No such part	50.00 FS	*- FS
44	1		*FRONT CHROME GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*RECORDING CAMERA W/BRACKET	Broken	580.00 FS	*580.00 FS
46	1		*SLIDING DOOR (FRONT)	Dented	4,800.00 FS	*2,200.00 FS
47	1		*SLIDING RAILS LOWER	Not Damaged	742.30 FS	*- FS
48	1		*SLIDING DOOR LOCK	Dented	285.32 FS	*150.00 FS
49	1		*SLIDING DOOR HANDLE	Dented	88.00 FS	*88.00 FS
50	1		*FRONTDOOR FRAME	Dented	1,200.00 FS	*1,000.00 FS
51	1		*ALUMINIUM PLATE	Dented	1,600.00 FS	*1,600.00 FS
52	1		*SAFETY BAR	Bent	950.00 FS	*480.00 FS
53	1		*STEP BAR	Bent	600.00 FS	*300.00 FS
54	2		*FRONT RIM	Not Damaged	2,000.00 FS	*- FS
55	2		*FRONT TYRE	Not Damaged	1,100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

12/29/22, 3:45 PM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	43,171.00	14,063.70
				- List Item Discount on L Items 15.00/15.00% (S\$)	4,272.81	1,133.36
				Total Parts (S\$)	38,898.19	12,930.34
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R FRONT DOOR COMPONENT	New	200.00	80.00
2	R&R FRONT WINDSCREEN	New	300.00	120.00
3	R&R FRONT DASHBOARD	New	600.00	0.00
4	R&R FRONT UNDER CARRIAGE	New	850.00	400.00
5	R&R FRONT TYRE & BALANCING	New	200.00	0.00
6	WHEEL ALIGNMENT	New	300.00	150.00
7	R&R SLIDING DOOR	New	300.00	0.00
8	CHECK WIRING	New	100.00	30.00
9	UPHOLSTERY	New	300.00	0.00
10	PANEL BEATING	New	3,800.00	1,200.00
11	RUST PROOFING	New	200.00	0.00
12	SPRAY PAINTING	New	3,800.00	1,200.00
13	LABOUR	New	1,000.00	1,000.00
Gross Labour Cost (S\$)			11,950.00	4,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >