

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21010444/RES3Q2**Date:** 07/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210020626
Claimant Vehicle No :	SHC4103A	Insured Vehicle No :	SMY3307K
Date of Loss:	06/10/2021	Nature of Claim:	TP
		Claim No:	1768799735SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4103A		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR6589835
Reg. Date:	08/04/2016 (Man. Year: 2015)	Chassis No:	JTDKN36U505767805
Colour:	Maroon	Odometer:	435621 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,410.94	2,986.76	25,424.18	89.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,815.00	1,720.00	2,095.00	54.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,225.94	4,706.76	27,519.18	85.39
Approved Total (Overridden) (S\$)		4,100.00		
Nett Amount (S\$)	32,225.94	4,100.00	28,125.94	87.28
+ Car Rental (13.0 x S\$65.00/day) (S\$)		845.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		4,952.00		
Global Sum Settlement (S\$)		4,950.00		

INSPECTION

Date of Assignment:	08/10/2021	
Date Inspected:	08/10/2021	Inspected At: 60 WOODLANDS INDUSTRIAL PARK E4
Estimated Period of Repair:	7.0 days	Repairer: Smrt Automotive Services Pte Ltd (HQ)

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRAKET ,FR TURN LOWER LH (DISC 25%)	Cracked	26.00 F	*19.50 F
2	1		*BRAKET ,FR TURN CENTER LH (DISC 25%)	Cracked	58.20 F	*43.65 F
3	1		*BRAKET ,FR TURN UPPER LH (DISC 25%)	Cracked	24.40 F	*18.30 F
4	1		*FENDER FRT/LH (DISC 25%)	Buckled	723.40 F	*542.55 F
5	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
6	1		*FENDER LINER FRT/LH(DISC 25%)	Deformed	171.70 F	*128.78 F
7	1		*BUMPER FRT (DISC 25%)	Deformed	482.00 F	*361.50 F
8	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
9	1		*BUMPER SUPPORT F/LH (DISC 25%)	Deformed	76.40 F	*57.30 F
10	1		*BUMPER ENERGY ABSORBER FRT (DISC 25%)	Necessary	78.80 F	*59.10 F
11	1		*FENDER LINDER PAD ,FR WHEEL ,LH (DISC 25%)	Necessary	49.30 F	*36.98 F
12	1		*BUMPER LIP FRT (DISC 25%)	Deformed	139.60 F	*104.70 F
13	1		*HEAD LAMP LH (DISC 10%)	Broken	945.20 F	*850.68 F
14	1		*LENS & BODY FR TURN LH (DISC 10%)	Cracked	511.80 F	*460.62 F
15	1		*FOG LAMP LH (DISC 10%)	Scratched	280.10 F	*252.09 F
16	1		*UNDER COVER SIDE /LH	Not Necessary	46.10 F	*- F
17	1		*BUMPER FRT ABSORBER LOWER	Not Necessary	127.70 F	*- F
18	1		*BUMPER LIP FRT	Not Necessary	139.60 F	*- F
19	1		*GRILLE ,RADIATOR LOWER NO.2	Not Necessary	94.60 F	*- F
20	1		*GRILLE ,RADIATOR	Not Necessary	310.60 F	*- F
21	1		*COVER ,RADIATOR	Not Necessary	122.80 F	*- F
22	1		*HOOD END PANEL SEAL	Not Necessary	35.50 F	*- F
23	1		*HOOD HINGE LH	Not Necessary	55.90 F	*- F
24	1		*HOOD HINGE RH	Not Necessary	55.90 F	*- F
25	1		*HEAD LAMP RH	Not Necessary	945.20 F	*- F
26	1		*HOSE ,INVERTER NO.1	Not Necessary	80.00 F	*- F
27	1		*HOSE ,INVERTER COOLING NO.5	Not Necessary	125.30 F	*- F
28	1		*SUPPORT RADIATOR LH	Not Necessary	17.70 F	*- F
29	1		*SUPPORT RADIATOR RH	Not Necessary	54.50 F	*- F
30	1		*RADIATOR LOWER SUPPORT	Not Necessary	876.30 F	*- F
31	1		*RADIATOR ASSY	Not Necessary	1,496.90 F	*- F
32	1		*INVERTER BRACKET TRAY	Not Necessary	251.60 F	*- F
33	1		*INVERTER W CONVERTER	Not Necessary	5,390.20 F	*- F
34	1		*COOLANT RESERVE TANK	Not Necessary	395.30 F	*- F
35	1		*FENDER PROTECTOR FRT/LH UPPER	Not Necessary	46.10 F	*- F
36	1		*PROTECTOR FRONT FENDER SIDE PANEL LH	Not Necessary	114.50 F	*- F
37	1		*SEAL ,FRONT FENDER TO COWL SIDE LH	Not Necessary	15.20 F	*- F
38	1		*FENDER LINER PAD ,FR WHEEL LH	Not Necessary	49.30 F	*- F
39	1		*FENDER APRON SUB FRT/LH	Not Necessary	637.80 F	*- F
40	1		*TYRE	Not Necessary	126.74 F	*- F
41	2		*STABILIZER BAR LINK FRT/RH/LH	Not Necessary	195.00 F	*- F
42	1		*STEERING KNUCKLE LH FRT	Not Necessary	580.80 F	*- F
43	1		*TIE ROD END LH	Not Necessary	159.30 F	*- F
44	1		*WHEEL HUB FRT	Not Necessary	549.70 F	*- F
45	1		*FUSE BLOCK ,ENGINE ROOM	Not Necessary	148.50 F	*- F
46	1		*FUSE BLOCK ,COVER LOWER	Not Necessary	18.50 F	*- F
47	1		*FUSE BLOCK ,TOP COVER	Not Necessary	82.30 F	*- F
48	1		*PILLAR ,FR BODY ,LH	Not Necessary	363.10 F	*- F
49	1		*BUMPER SUPPORT F/RH	Not Necessary	76.40 F	*- F
50	1		*BUMPER REINFORCEMENT FRT	Not Necessary	498.40 F	*- F
51	1		*ARM SUB-ASSY ,FR BUMPER LH	Not Necessary	250.40 F	*- F
52	1		*ARM SUB-ASSY ,FR BUMPER RH	Not Necessary	250.40 F	*- F
53	1		*DEFLECTOR ,RADIATOR RH	Not Necessary	83.50 F	*- F
54	1		*DEFLECTOR ,RADIATOR LH	Not Necessary	77.00 F	*- F
55	1		*COVER ,FR BUMPER HOLE LH	Not Necessary	18.50 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*BUMPER GRILLE SUB-ASSY ,LOWER	Not Necessary	311.10 F	*- F
57	1		*WIRE ENGINE ROOM NO.3	Not Necessary	242.00 F	*- F
58	1		*WIRE ENGINE ROOM	Not Necessary	5,567.10 F	*- F
59	1		*HOOD PANEL	Repair	748.10 F	*- F
60	1		*SUPPORT SUB-ASSY	Repair	1,460.40 F	*- F
61	1		*WHEEL DISC ,FRONT	Repair	1,484.20 F	*- F
					Total Parts (\$\$)	28,410.94 2,986.76

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,045.00	700.00
2	SPRAY PAINT	New	2,234.00	850.00
3	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	60.00
4	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	30.00
5	TO REPLACE SUNDRY PARTS	New	100.00	0.00
6	TO CHECK WIRING AND SYSTM E FUNCTION	New	80.00	40.00
7	TO WASH AND VACUUM	New	60.00	0.00
8	TOWING CHARGE	New	56.00	40.00
Gross Labour Cost (\$)			3,815.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >