

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21010447/AVY3E2

Date: 27/01/2022

REFERENCE

Insured/Claimant: CHEW SIN WAN (ZHOU XINHUAN) Policy No: 1900167318-01
Date of Loss: 04/10/2021 Nature of Claim: OD Claim No: 3693865279SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLF6888S
Make & Model: AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A) Engine No: DAX057355
Reg. Date: 27/09/2019 (Man. Year: 2019) Chassis No: WAUZZZF1K2110123
Colour: White Odometer: 37554 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$170,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,243.00	20,570.16	13,672.84	39.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,364.00	8,064.00	5,300.00	39.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	47,607.00	28,634.16	18,972.84	39.85
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	46,607.00	27,634.16	18,972.84	40.71
+ GST 7.00/7.00% (S\$)	3,262.49	1,934.39	1,328.10	40.71
Nett Amount (S\$)	49,869.49	29,568.55	20,300.94	40.71

INSPECTION

Date of Assignment: 12/10/2021
Date Inspected: 11/10/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,362.00 FS	*1,089.60 FS
2	1		*FRONT BUMPER CONNECTING PIECE	Not Necessary	205.00 FS	*- FS
3	1		*FRONT BUMPER FIXING PARTS	Not Necessary	293.00 FS	*- FS
4	1		*FRONT BUMPER SECURING STRIP - RH	Not Necessary	38.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - RH	Deformed	113.00 FS	*90.00 FS
6	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	144.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Torn	763.00 FS	*610.00 FS
8	1		*FRONT BUMPER UNDERRUN BAR	Not Necessary	518.00 FS	*- FS
9	1		*FRONT BUMPER CLOSING ELEMENT	Deformed	173.00 FS	*138.40 FS
10	1		*FRONT RADIATOR GRILLE	Cut	3,530.00 FS	*2,824.00 FS
11	1		*QUATTRO EMBLEM	Not Necessary	106.00 FS	*- FS
12	1		*FRONT RADIATOR STRIKER PLATE	Cracked	244.00 FS	*194.80 FS
13	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Deformed	581.00 FS	*464.40 FS
14	1		*FRONT BUMPER AIR GUIDE END CAP - RH	Deformed	92.00 FS	*73.20 FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Deformed	177.00 FS	*141.60 FS
16	1		*FRONT BUMPER CARRIER	Dented	981.00 FS	*784.40 FS
17	1		*FRONT BUMPER CARRIER BRACKET - RH	Not Necessary	257.00 FS	*- FS
18	1		*FRONT BUMPER CARRIER GUIDE SECTION - RH	Not Necessary	39.00 FS	*- FS
19	1		*FRONT BUMPER TOP COVER	Deformed	129.00 FS	*102.80 FS
20	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
21	1		*AIR CONDITIONER STICKER	Necessary	20.00 FS	*15.52 FS
22	1		*HORN	Not Necessary	195.00 FS	*- FS
23	1		*FRONT PARKING AID SENSOR - RH INNER (NPA)	Not Necessary	0.00 FS	*- FS
24	1		*FRONT PARKING AID SENSOR - RH OUTER (NPA)	Not Necessary	0.00 FS	*- FS
25	4		*FRONT PARKING AID SENSOR SEAL	Not Necessary	14.00 FS	*- FS
26	1		*SET FRONT BUMPER WIRING	Not Necessary	409.00 FS	*- FS
27	1		*FRONT FENDER - RH	Buckled	1,427.00 FS	*1,141.60 FS
28	1		*FRONT FENDER ATTACHMENT PART	Not Necessary	66.00 FS	*- FS
29	1		*FRONT FENDER BRACE - RH	Bent	225.00 FS	*179.60 FS
30	1		*FRONT FENDER BRACKET - RH	Not Necessary	18.00 FS	*- FS
31	1		*FRONT FENDER TOP COVER - RH	Not Necessary	31.00 FS	*- FS
32	1		*FRONT FENDER PANEL COVER - RH	Not Necessary	40.00 FS	*- FS
33	1		*FRONT BONNET	Dented	4,058.00 FS	*3,246.40 FS
34	1		*FRONT BONNET ATTACHEMENT PART	Not Necessary	141.00 FS	*- FS
35	1		*FRONT BONNET IMPACT PROTECTION - LH / RH	Necessary	56.00 FS	*43.68 FS
36	1		*FRONT BONNET STRIKER - RH	Not Necessary	120.00 FS	*- FS
37	1		*FRONT BONNET LOCK	Not Necessary	214.00 FS	*- FS
38	1		*FRONT BONNET BOWDEN CABLE	Not Necessary	58.00 FS	*- FS
39	1		*FRONT BONNET RELEASE CABLE COVER	Not Necessary	10.00 FS	*- FS
40	1		*FRONT BONNET RELEASE LEVER	Not Necessary	14.00 FS	*- FS
41	1		*MOUNTING FOR HEADLIGHT - RH	Cracked	118.00 FS	*94.40 FS
42	1		*HEADLIGHT - RH	Cracked	8,191.00 FS	*6,552.80 FS
43	1		*HEADLIGHT POWER MODULE - RH	Not Necessary	758.00 FS	*- FS
44	1		*HEADLIGHT LED WITH HEAT SINK - RH	Not Necessary	1,098.00 FS	*- FS
45	1		*HEADLIGHT CONTROL UNIT	Not Necessary	736.00 FS	*- FS
46	1		*HEADLIGHT HOSE - RH	Not Necessary	39.00 FS	*- FS
47	1		*HEADLIGHT LIFT CYLINDER - RH	Not Necessary	140.00 FS	*- FS
48	1		*HEADLIGHT WASHER HOSE - RH	Not Necessary	125.00 FS	*- FS
49	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	278.00 FS	*- FS
50	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PART	Not Necessary	38.00 FS	*- FS
51	1		*FRONT WHEEL SPOILER	Torn	155.00 FS	*123.60 FS
52	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,264.00 FS	*1,011.20 FS
53	1		*S LINE EMBLEM	Necessary	128.00 FS	*102.00 FS
54	1		*RADIATOR LOCK CARRIER	Cracked	1,400.00 FS	*1,120.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*RADIATOR LOWER BRACE - RH	Not Necessary	57.00 FS	*- FS
56	1		*RADIATOR BRACKET	Not Necessary	16.00 FS	*- FS
57	1		*INTER COOLER HOSE - RH	Not Necessary	315.00 FS	*- FS
58	1		*COOLANT (6PCS)	Necessary	266.00 FS	*212.64 FS
59	1		*FRONT RADIATOR AIR GUIDE - RH	Not Necessary	58.00 FS	*- FS
60	2		*FRONT RADIATOR AIR GUIDE - UPPER / LOWER	Not Necessary	96.00 FS	*- FS
61	1		*FRONT RADIATOR AIR GUIDE - CENTER	Not Necessary	42.00 FS	*- FS
62	1		*FRONT RADIATOR ASSEMBLY	Not Necessary	534.00 FS	*- FS
63	1		*NOISE INSULATION	Not Necessary	915.00 FS	*- FS
64	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
65	1		*SUNDRIES	Necessary	400.00 FS	*30.88 FS
66	1		*BONNET IMPACT PROTECTION-CENTER (Supplementary)	Necessary	28.00 FS	*22.00 FS
67	1		*HORN BRACKET-RH (Supplementary)	Bent	42.00 FS	*32.96 FS
68	1		*COOLANT HOSE WITH QUICK RELEASE (Supplementary)	Damaged	71.00 FS	*56.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	34,243.00	20,570.16
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO RENEW AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,700.00	1,700.00
4	TO DISMANTLE RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	3,000.00
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER, BONNET AND BOTH FRONT WHEEL ARCH TRIM	New	4,800.00	2,250.00
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (S\$)			13,364.00	8,064.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >