

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJS6912K Volkswagen Golf

No	Qty	Parts Description	Estimated Parts Price
----	-----	-------------------	-----------------------

1	1	Front left headlamp	\$ 1,297.30 ?
2	1	Front bumper assy	\$ 1,500.80 <i>in</i>
3	1	Front bumper left side retainer	\$ 143.80 <i>no</i>
4	1	Front left fender	\$ 688.80 <i>bd</i>
5	1	Front left fender inner cowling	\$ 188.80 ?
6	1	Front left wing mirror complete assy	\$ 908.80 X
7	1	Front left suspension assy	\$ 1,190.70 # ?
8	1	Front left wheel hub bearing	\$ 361.80 ?
9	1	Front left knuckle arm	\$ 864.50 ?
10	1	Front left lower arm carrier	\$ 637.20 X
11	1	Front left tie rod end	\$ 169.40 X
12	1	Front left ball joint	\$ 150.20 X
13	1	Front left stabilizer bar	\$ 488.80 X
14	1	Front left stabilizer bar linkage	\$ 169.90 X
15	1	Front power steering rack and pinion assy	\$ 3,200.90 X
16	1	Front left ABS Sensor	\$ 198.80 X
17	1	Front left drive shaft	\$ 1,288.90 X
18	1	Front left brake disc	\$ 268.70 X

less 10%

\$ 13,718.10

\$ 1,371.81

\$ 12,346.29

Special Nett Items

1	10	Front bumper clips	
2	4	Front left fender inner cowling clips	\$ 60.00 <i>30 net</i>
3	1	Front left sports rim	\$ 40.00 <i>10 net</i>
4	1	Front left tyre	\$ 950.00 <i>ent - 600</i>
5	1	Front no plate with garnish	\$ 450.00 X
			\$ 100.00 X
			\$ 1,600.00

Total parts

\$ 13,946.29

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJS6912K Volkswagen Golf

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front left affected area and replace front left damaged parts.	\$ 1,200.00 <i>400 500</i>
2	To putty and spray painting front left portion.	\$ 1,200.00 <i>500</i>
3	To check wiring and focus front headlamp.	\$ 50.00 <i>30</i>
4	To apply anti rust proofing to front left affected area.	\$ 140.00 <i>30</i>
5	To remove and install front left undercarriage parts.	\$ 350.00 <i>150? p lub</i>
6	To balance front left wheel.	\$ 50.00 <i>30</i>
7	To conduct wheel alignment.	\$ 120.00 <i>80 repair</i>
8	To synchronise front left wing mirror for function.	\$ 100.00 <i>x</i>
9	Towing service.	\$ 100.00 <i>x</i>
Total labour :		\$ 3,310.00

Total parts : \$ 13,946.29

Total labour : \$ 3,310.00

Total repair cost : \$ 17,256.29

Tanpin 97495746
Wp' 12/10/21 @ 1150
c/s Resurvey after repair
Tanpin C/Khantoon
04 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: