| ASS. REC. BY: Tay JUL - REF: CS/ HSM | 21010480/T, ty3 |
|--|--|
| | IGNMENT COE 2 2 |
| From: Date: | Veh No: 35569/2K. Yr Regn: 2009 Aug C |
| Estimated Cost: | Type: M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / |
| OD I WS I TP RES I OD RES I EVA I INV I MV | Truck/Traller or |
| To Inspect Vehicle Na: | Máke: Vollowaya Golf co 1390. |
| at Workshop m/s | |
| of _ | |
| Insured: | Sp.Reading 75246 T/Radio: Insured / Std / NI / NA Eng/No: |
| Policy No. | C/NO: WVW ZZZ /WZ·AWO/8/35 |
| Claims No. | Gen. Cond: Good/Fair/Poor/Burnt |
| Sum Insured: Excess: | Steering: Inorder / Jammed / Leaked / Burnt or |
| (Client's Record) | Brake: Inorder Jammed / Leaked / Burnt or |
| Make of Veh: | Modi: Nil / S/Rip / STD A/Rim or , |
| | Tyre Size: F: 225/40R/8 |
| (Policy Condition) | R: 7 9. |
| Remark: The veh had commenced its repair at the time of inspection. N/S O/S | BS / DUN / EXNOVA / GY / FS / LIZA MICDOHTSU / PIR / SUMI / TOYO / YOKO OF |
| Bal. or Market Value: 45016 | |
| IDAC Accident Rport: Consistent? : Yes or No | R/Bal 6 |
| GIA / PR Seen: Consistent? : Yes or No | Weal. |
| Est. Repairs: days Res.: Yes or No | Doal. 6 mm |
| Lum Sum: % 3 Val.: Yes or No | Survey held at 751 |
| CA / REV / REP. / 24 HRS | Des. of Damages: Frt / Rear / O/S / N/S / U/C, / Rooftop or |
| · Vehicle: IN / OUT | Tut Me 2/C |
| Date: Person Contacted: Date / Time Action / Instruction | The U/C / Chassis frame / Body Structure affected due to collision. |
| Action / miss defect | |
| | |
| COR Is\$4700, 4 days, | |
| | |
| RED: 12556.29;72% | |
| | |
| | |
| Date/Time, File Pass to? | |
| | Days Of Repair: 4 |
| Dale/Tims, File Return to? | Resurvey No. of Trip: |
| 2) | Survey Fee: Transportation: |
| Add Fee | The map (a) |
| Republicania; | : Interview (\$) _s+Rs_si : Tech Inve (\$) Photos |
| Lump Sum / Le.A. C: | : Tech. Invs (3 |

TSL Auto Garage Blk 4 Joo Chiat Complex #12-1171 Joo Chiat Road Singapore 420004

SJS6912K Volkswagen Golf

| | SJS6912K Volkswagen Golf | | | Estimated |
|----|--------------------------|---|-----------------------|-------------------------------|
| No | Qty | Parts Description | | Parts Price |
| 1 | 1 | Front left headlamp | \$ | 1,297.30 |
| 2 | 1 | Front bumper assy | \$ | 1,500.807 |
| 3 | 1 | Front bumper left side retainer | \$ | 1,500.807 143.80 688.80 |
| 4 | 1 | Front left fender | \$ | 688.80 |
| 5 | 1 | Front left fender inner cowling | \$ | 188.80 |
| 6 | 1 | Front left wing mirror complete assy | \$ | 908.80 |
| 7 | 1 | Front left suspension assy | \$ | 1,190.70 |
| 8 | 1 | Front left wheel hub bearing | \$ | 361.80 |
| 9 | 1 | Front left knuckle arm | \$ | 864.507 |
| 10 | 1, | Front left lower arm carrier | \$ | 637.20 ₹ |
| 11 | 1 | Front left tie rod end | \$ | 169.40 × |
| 12 | 1 | Front left ball joint | \$ | 150.20 |
| 13 | 1 | Front left stabilizer bar | \$ | 488.80 x |
| 14 | 1 | Front left stabilizer bar linkage | \$ | 169.90 × |
| 15 | 1 | Front power steering rack and pinion assy | \$ | 3,200.90 > |
| 16 | 1 | Front left ABS Sensor | \$ | 198.80 🗸 |
| 17 | 1 | Front left drive shaft | \$ | 1,288.90 × |
| 18 | 1 | Front left brake disc | \$ | 268.70 ⊀ |
| | | 1 1007 | \$ | 13,718.10 |
| | | less 10% | \$ | 1,371.81 |
| | | Special Nett Items | \$ | 12,346.29 |
| 1 | 10 | Front bumper clips | | 12,570.29 |
| 2 | 4 | Front left fender in a second | \$ | ۇ 60.00 |
| 3 | 1 | Front left fender inner cowling clips Front left sports rim | \$ | ~ |
| 4 | 14 | Front left tyre | \$ | 40.00 l 950.00 w |
| 5 | | Front no plate with garnish | | |
| | | Plate with gainsn | \$ | 450.00 X |
| | | | \$ <u>\$</u> \$ | 100.00 x |
| | , | Total parts | | 1,600.00 |
| | | - | \$ | 13,946.29 |

TSL Auto Garage Blk 4 Joo Chiat Complex #12-1171 Joo Chiat Road Singapore 420004

SJS6912K Volkswagen Golf

| Section 1979 | The state of the s | - Sub-market | AND UNION THE PROPERTY OF THE PARTY. |
|--------------|--|--------------|--------------------------------------|
| | |] | Labour |
| No | Description | (| Charges |
| 1 | Labour for panel beating, cut, weld, straighten front left affected | \$ | 1,200.00 400500 |
| | area and replace front left damaged parts. | | Con |
| 2 | To putty and spray painting front left portion. | \$ | 1,200.00 500 |
| 3 | To check wiring and focus front headlamp. | \$ | 50.00 30 |
| 4 | To apply anti rust proofing to front left affected area. | \$ | 140.00 30 |
| 5 | To remove and install front left undercarriage parts. | \$ | 350.00 (5°?) hut 50.00 20 |
| 6 | To balance front left wheel. | \$ | |
| 7 | To conduct wheel alignment. | \$ | 120.00 BO Nepon |
| 8 | To synchronise front left wing mirror for function. | \$ | 100.00× |
| 9 | Towing service. | \$ | 100.00 × |
| | Total labour: | \$ | 3,310.00 |

Total parts: \$ 13,946.29

Total labour: \$ 3,310.00

Total repair cost: \$ 17,256.29

Tanfor 97495744 WP' 12/W/218 1150 Lls Resum after repair tanfor Clochautown of days

LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: