

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010453/TVY3N2**Date:** 22/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00088752100

Claimant Vehicle No : GBK4099H **Insured Vehicle No :** GBJ8048J

Date of Loss: 07/10/2021 Nature of Claim: TP Claim No: SNM21D205733/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK4099H**

Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KDB036786

Reg. Date: 15/07/2020 (Man. Year: 2020) Chassis No: JTFAT35Y10K215118

Colour: Silver Odometer: 68871 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75R15 Rear Tyre Size: 155R12

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,611.25	4,366.57	11,244.68	72.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,400.00	2,250.00	4,150.00	64.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,011.25	6,616.57	15,394.68	69.94
Approved Total (Overridden) (\$\$)		5,300.00		
(\$\$)	22,011.25	5,300.00	16,711.25	75.92
+ GST 7.00/7.00% (\$\$)	1,540.79	371.00	1,169.79	75.92
Nett Amount (\$\$)	23,552.04	5,671.00	17,881.04	75.92

INSPECTION

Date of Assignment: 14/10/2021

Date Inspected: 12/10/2021 Inspected At: 56 LOYANG WAY, #04-04
LOYANG ENTERPRISE BUILDING
REPAIRER: AP AUTOMOTIVE SERVICES PTE LTD

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Mar 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK4099H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WIPER PANEL	Bent	275.00 FL	*256.00 FL
2	1		*FRONT CENTER PANEL	Bent	1,103.00 FL	*920.00 FL
3	1		*FRONT CENTER PANEL EMBLEM-DYNA	Necessary	66.00 FL	*66.00 FL
4	1		*FRONT SIDE PANEL LH	Missing	285.00 FL	*217.80 FL
5	1		*FRONT SIDE PANEL INNER PANEL LH	Repair	451.00 FL	*- FL
6	1		*FRONT SIDE MIRROR ASSY LH	Broken	815.00 FL	*455.30 FL
7	1		*FRONT GRILLE	Cracked	513.00 FL	*388.85 FL
8	1		*FRONT GRILLE LOGO-TOYOTA	Necessary	76.00 FL	*76.00 FL
9	1		*HEADLAMP LH	Cracked	726.00 FL	*450.00 FL
10	1		*HEADLAMP BRACKET LH	Cracked	216.00 FL	*95.00 FL
11	1		*FRONT BUMPER	Repair	497.00 FL	*- FL
12	1		*FRONT BUMPER FOG LAMP GARNISH LH	Not Necessary	90.00 FL	*- FL
13	1		*FRONT BUMPER BRACKET	Not Necessary	412.00 FL	*- FL
14	1		*FRONT DOOR LH	Bent	1,613.00 FL	*1,208.00 FL
15	1		*FRONT DOOR STEP GARNISH LH	Not Necessary	411.00 FL	*- FL
16	1		*FRONT DOOR STEP PANEL LH	Not Necessary	671.00 FL	*- FL
17	1		*FRONT DOOR WINDOW LH	Cracked	699.00 FL	*408.15 FL
18	1		*FRONT DOOR WINDOW MOULDING LH	Cut	103.00 FL	*103.00 FL
19	1		*FRONT DOOR INNER WINDOW MOULDING LH	Not Necessary	115.00 FL	*- FL
20	1		*FRONT DOOR LOCK LH	Not Necessary	377.00 FL	*- FL
21	1		*FRONT DOOR LOCK CATCH LH	Not Necessary	58.00 FL	*- FL
22	1		*FRONT DOOR INNER BOARD LH	Not Necessary	491.00 FL	*- FL
23	1		*FRONT DOOR POWER WINDOW MOTOR LH	Not Necessary	731.00 FL	*- FL
24	1		*FRONT DOOR WINDOW REGULATOR LH	Not Necessary	404.00 FL	*- FL
25	1		*FRONT DOOR CHECKER LH	Not Necessary	184.00 FL	*- FL
26	1		*FRONT DOOR HINGE LH	Bent	146.00 FL	*120.00 FL
27	1		*FRONT DOOR WEATHERSTRIP LH	Cut	195.00 FL	*146.00 FL
28	1		*FRONT DOOR INNER WEATHERSTRIP LH	Necessary	155.00 FL	*112.00 FL
29	1		*FRONT COWLING LH	Not Necessary	128.00 FL	*- FL
30	1		*A PILLAR LH	Repair	1,046.00 FL	*- FL
31	1		*FRONT DOOR PILLAR LH	Repair	1,074.00 FL	*- FL
32	1		*FRONT ABSORBER LH	Not Necessary	115.00 FL	*- FL
33	1		*FRONT LOWER ARM LH	Not Necessary	667.00 FL	*- FL
34	1		*FRONT KNUCKLE LH	Not Necessary	607.00 FL	*- FL
35	1		*FRONT KNUCKLE BEARING LH	Not Necessary	117.00 FL	*- FL
36	1		*FRONT BEARING HUB	Not Necessary	285.00 FL	*- FL
37	1		*FRONT RIM LH	Not Necessary	698.00 FL	*- FL
38	1		*FRONT SIDE PANEL CLIPS	Necessary	50.00 FS	*20.00 FS
39	1		*FRONT CENTER PANEL SEALANT	Necessary	120.00 FS	*40.00 FS
40	1		*FRONT CENTER PANEL STICKER	Necessary	500.00 FS	*180.00 FS
41	1		*FRONT NUMBER PLATE	Not Necessary	80.00 FS	*- FS
42	1		*FRONT DOOR STICKER-COMPANY REG LH	Necessary	300.00 FS	*30.00 FS
43	1		*FRONT DOOR STICKER-COMPANY LOGO LH }	Necessary	800.00 FS	*300.00 FS
44	1		*FRONT DOOR STICKER-COMPANY NAME LH }	Necessary	700.00 FS	*- FS
45	1		*FRONT DOOR INNER BOARD CLIPS	Necessary	100.00 FS	*30.00 FS
46	1		*FRONT TYRE LH	Not Necessary	500.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					19,765.00	5,622.10
- List Item Discount on L Items 25.00/25.00% (S\$)					4,153.75	1,255.53
Total Parts (S\$)					15,611.25	4,366.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,200.00	1,000.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,600.00	1,000.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	New	150.00	30.00
4	TO RNR FRONT SIDE MIRROR	New	300.00	60.00
5	TO RNR FRONT DOOR MECHANISM	New	800.00	60.00
6	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	0.00
7	TO RNR UNDERCARRIAGE	New	250.00	0.00
8	TO CHECK WHEEL BALANCING	New	250.00	0.00
9	TO PERFORM RUST PROOFING	New	300.00	40.00
10	TO VACUUM AND CLEAN GLASSES	New	300.00	60.00
Gross Labour Cost (\$\$)			6,400.00	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >