11/26/21, 11:56 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010455/AUY3N2

26/11/2021 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMPCSNW00028022105

Claimant Vehicle No:

SJR6525A

Insured

SGC531K

Date of Loss:

09/10/2021

Vehicle No: Nature of Claim: TP

Engine No:

Chassis No:

Odometer:

SNM21D205756/C02/TANKW

1NZX928971

210789 km

MR053HY9305119306

DESCRIPTION & IDENTIFICATION OF VEHICLE

SJR6525A Reg No:

Make & Model: TOYOTA VIOS E, 1.5 (A)

Reg. Date: 03/07/2009 (Man. Year: 2009)

Colour: White

Engine Capacity: 1497 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 175/65R15 Rear Tyre Size: 175/65R15 Front Left Side: Rear Left Side: Habilead 6 mm Habilead 6 mm Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,947.20	2,007.82	939.38	31.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,670.00	1,360.00	310.00	18.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,617.20	3,367.82	1,249.38	27.06
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	4,617.20	2,700.00	1,917.20	41.52

INSPECTION

Date of Assignment: 14/10/2021

Heng Kee Workshop (HQ) Date Inspected: 12/10/2021 Inspected At:

BLK 1033 EUNOS AVENUE 5A #01-31

Singapore 409703

Estimated Period of Repair: 4.0 days

Adjuster: **ADRIAN LING** Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Nov 2021)

Parts: 143 TOYOTA VIOS E 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJR6525A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MIRROR	Damaged	987.10 F	*987.10 FL
2	1		*REAR BUMPER	Deformed	478.90 F	*478.90 FL
3	1		*REAR SIDE BRAKER	Necessary	61.10 F	*61.10 FL
4	1		*REAR DOOR OUTER MOULDING	Not Necessary	230.10 F	*- FL
5	1		*REAR DOOR COMEL RUBBER	Cut	189.90 F	*189.90 FL
6	1		*REAR TAILLAMP	Cut	320.10 F	*320.10 FL
7	1		*REAR SPORT RIM	Cut	680.00 FS	*480.00 FS
F=Fra	nchise	part. S=SpcNe	tt. L=ListItemDisc.			
				Sub Total (S\$)	2,947.20	2,517.10
	- List Item Discount on L Items 0.00/25.00% (S\$)			0.00	509.28	
				Total Parts (S\$)	2,947.20	2,007.82
			Report was unsubmitte	ed during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO WIRE LABOUR CHARGE	New	100.00	30.00
2	TO WHEEL ALIGNMENT	New	120.00	80.00
3	TO REVERSE SENSOR LABOUR CHARGES	New	120.00	50.00
4	TO SPRAY PAINTING	New	850.00	800.00
5	TO LABOUR CHARGES	New	480.00	400.00
		Gross Labour Cost (S\$)	1,670.00	1,360.00
	Report was un:	submitted during this print-out.		

< END OF ESTIMATES >