

HENG KEE WORKSHOP

BLK 1033 EUNOS AVE 5A #01-31 SINGAPORE 409703
HP: 8156 2761

Specialises In Accident Repair, Insurance Claims & Reporting, Service Repair, Panel Beating & Spray Painting Of Automotive Vehicles.

TP Ching

Hui Zhen

SJR6525A

12-10-21

Front Mirror 987.10 ✓ Damaged.

Rear Bumper 478.90 ✓ Del d

Rear Side Braker 81.10 ✓ nel

Rear Door Outer Moulding 230.10 14 x

Rear Door Corner Rubber 189.90 ✓ cut

Rear Taillamp 320.10 ✓ cut

Rear Sport Rim 680 480(SN) cut ✓

To Wire labour charges 100 30

To Wheel Alignment 120 80

To Reverse Sensor labour charges 120 50

To Spray Painting 850 800

To Labour charges 480 400

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
H/s 12/10/21
04 Days

List 2037.10
less 25%: 1527.82
SN: 480
Labour: 1360
total: 3367.82

2/S: 2.7K
04 Days