

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4779U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
2	REAR BUMPER SIDE BRACKET LH/RH @\$55.80	SERVICEABLE	111.60	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	394.80	-
1	REAR BUMPER STAY LH	SERVICEABLE	138.10	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER LOWER COVER	SERVICEABLE	155.00	-
1	BUMPER TOW COVER	SERVICEABLE	98.80	-
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	41.45	-
1	REAR BUMPER FOG LAMP	SERVICEABLE	201.10	-
	LESS 20% DISCOUNT		-414.70	-94.65
			1,658.80	378.60
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE W/HOLDER (SN)	SCRATCHED	55.00	55.00
1	REAR REVERSE SENSOR (SN)	SERVICEABLE	180.00	-
			235.00	55.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		560.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK WIRING AND LIGHTING.		60.00	20.00
	TUFF KOTE.		60.00	20.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	20.00
			1,040.00	660.00
	GRAND TOTAL		2,933.80	1,093.60





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS (CONFIRMED) 1,093.60

Report Ref No. NS/INC21010456/Vvcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser