

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010460/BVY3N2**Date:** 22/02/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00066852102

Claimant Vehicle No : SKL6550X **Insured Vehicle No :** GBD1345D

Date of Loss: 08/10/2021 Nature of Claim: TP Claim No: SNM21D205785/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKL6550X**

Make & Model: BMW 316I, 1.6 (A) Engine No: A027J577N13B16A

Reg. Date: 10/12/2013 (Man. Year: 2013) Chassis No: WBA3A160X0NS36114

Colour: Black Odometer: 158135 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40R18 Rear Tyre Size: 235/40R18

Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm

Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,074.79	4,969.10	7,105.69	58.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,120.00	1,830.00	62.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,024.79	6,089.10	8,935.69	59.47
Approved Total (Overridden) (S\$)		4,850.00		
(S\$)	15,024.79	4,850.00	10,174.79	67.72
+ GST 7.00/7.00% (S\$)	1,051.74	339.50	712.24	67.72
Nett Amount (S\$)	16,076.53	5,189.50	10,887.03	67.72

INSPECTION

Date of Assignment: 07/02/2022

Date Inspected: 12/10/2021 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Feb 2022)
Parts:	143	BMW 316I 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL6550X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Damaged	1,190.05 FL	*- FL
2	1		*FRONT BUMPER	Broken	1,095.55 FL	*1,047.80 FL
3	1		*FRONT BUMPER RH PARKING SENSOR	Short Circuit	221.00 FL	*100.00 FL
4	1		*FRONT BUMPER RH FOG LAMP	No such part	294.95 FL	*- FL
5	1		*FRONT BUMPER RH FOG LAMP COVER	Dislodged	119.70 FL	*119.70 FL
6	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	41.40 FL	*41.40 FL
7	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	41.40 FL	*41.40 FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	598.20 FL	*- FL
9	1		*FRONT RH GRILLE	Not Damaged	186.50 FL	*- FL
10	1		*RH HEADLAMP	Cut	2,021.00 FL	*2,021.00 FL
11	1		*RH HEADLAMP WASHER NOZZLE COVER	Broken	59.15 FL	*59.15 FL
12	1		*RH HEADLAMP WASHER NOZZLE	Jammed	189.35 FL	*159.85 FL
13	1		*RH HEADLAMP LOWER BRACKET	Not Damaged	158.60 FL	*- FL
14	1		*FRONT RH FENDER	Dented	680.30 FL	*630.25 FL
15	1		*FRONT RH FENDER SPLASH SHIELD	Torn	267.40 FL	*136.40 FL
16	1		*WIPER WASHER TANK	Not Damaged	178.50 FL	*- FL
17	1		*FRONT RH SHOCK ABSORBER	Not Damaged	550.70 FL	*- FL
18	1		*FRONT RH LOWER ARM	Not Damaged	455.00 FL	*- FL
19	1		*FRONT RH KNUCKLE ARM	Not Damaged	609.00 FL	*- FL
20	1		*FRONT RH WHEEL BEARING	Not Damaged	531.50 FL	*- FL
21	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
22	1		*FRONT BUMPER LOWER SPOILER	Dislodged	1,100.00 FS	*800.00 FS
23	1		*FRONT BUMPER EMBLEM (AFTER MARKET)	Not Necessary	120.00 FS	*- FS
24	1		*FRONT RH SPORT RIM	Not Damaged	1,350.00 FS	*- FS
25	1		*FRONT RH TYRE	Not Damaged	350.00 FS	*- FS
26	1		*BRAKE FLUID	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,549.25	5,186.95
- List Item Discount on L Items 5.00/5.00% (\$)	474.46	217.85
Total Parts (\$)	12,074.79	4,969.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	600.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	400.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	40.00	0.00
5	RESET AND DIAGNOSE CONTROL UNIT AND FAULT CODE	New	320.00	120.00
6	CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
7	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	350.00	0.00
8	REFOCUS AND ADJUST HEADLAMP ASSY	New	60.00	0.00
Gross Labour Cost (\$)			2,950.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >