

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010464/KUY3N2**Date:** 25/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00034532100

Claimant Vehicle No : SJS8581T **Insured Vehicle No :** SLX2476D

Date of Loss: 10/10/2021 Nature of Claim: TP Claim No: SNM21D205773/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS8581T**

Make & Model: MERCEDES-BENZ B180, 1.3 PROGRESSIVE (A) Engine No: 26694030673830

Reg. Date: 11/09/2009 (Man. Year: 2009) Chassis No: WDD2452322J509575

Colour: Metallic Grey Odometer: 232194 km

Engine Capacity: 1699 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18

Front Left Side: Continental 8 mm Rear Left Side: Continental 8 mm

Front Right Side: Continental 8 mm Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,291.40	7,631.50	3,659.90	32.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,775.00	1,600.00	1,175.00	42.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,066.40	9,231.50	4,834.90	34.37
Approved Total (Overridden) (S\$)		7,350.00		
Nett Amount (S\$)	14,066.40	7,350.00	6,716.40	47.75

INSPECTION

Date of Assignment: 12/10/2021

Date Inspected: 12/10/2021 Inspected At: BLK 225 #07-579 ANG MO KIO AVE 1
SINGAPORE 560225
REPAIRER: MASSIVE TRADING & AUTO

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Oct 2021)

Parts: 144 MERCEDES-BENZ B180 1.3 PROGRESSIVE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJS8581T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S DOOR ASSY	Bent	2,100.00 FL	*2,100.00 FL
2	1		*FRONT N/S DOOR OUTER PROTECTOR	Bent	155.00 FL	*155.00 FL
3	1		*FRONT N/S DOOR FRAME BLACK STICKER	Necessary	105.00 FL	*105.00 FL
4	1		*FRONT N/S DOOR INNER TRIM BOARD	Mtg Cracked	1,920.00 FL	*1,915.00 FL
5	1		*FRONT N/S DOOR GLASS REGULATOR/MOTOR	Cracked	855.00 FL	*855.00 FL
6	1		*FRONT N/S DOOR INNER LOCK	Repair	455.00 FL	*- FL
7	1		*REAR N/S DOOR ASSY	Bent	2,195.00 FL	*2,195.00 FL
8	1		*REAR N/S DOOR OUTER PROTECTOR	Missing	135.00 FL	*135.00 FL
9	1		*REAR N/S DOOR FRAME BLACK STICKER	Necessary	105.00 FL	*105.00 FL
10	1		*REAR N/S DOOR INNER TRIM BOARD	Serviceable	1,920.00 FL	*- FL
11	1		*REAR N/S DOOR GLASS REGULATOR/MOTOR	Serviceable	855.00 FL	*- FL
12	1		*REAR N/S DOOR INNER LOCK	Repair	455.00 FL	*- FL
13	1		*REAR N/S FENDER PROTECTOR	Serviceable	85.00 FL	*- FL
14	1		*N/S ROCKER PANEL GARNISH	Dented/Cracked	550.00 FL	*550.00 FL
15	1		*FRONT N/S DOOR WEATHERSTRIP (50%)	Necessary	295.20 FS	*164.00 FS
16	1		*REAR N/S DOOR WEATHERSTRIP (50%)	Necessary	295.20 FS	*164.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,480.40	8,443.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,189.00	811.50
Total Parts (\$)	11,291.40	7,631.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,CUTTING & WELDING ETC	New	1,200.00	600.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	1,200.00	800.00
3	CHECK/RECONNECT WIRING	New	45.00	20.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	150.00	60.00
5	REMOVE/REFIT FRONT & REAR N/S DOOR GLASS,MECHANISM INNER LOCK,TRIM BOARD TO NEW DOOR	New	180.00	120.00
Gross Labour Cost (\$)			2,775.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >