#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21010465/EQF3E2

**Date:** 05/11/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070030258

Claimant Vehicle Program Control of the Control

No: FBK7656E Insured Vehicle No: SMS6263P

Date of Loss: 08/10/2021 Nature of Claim: TP Claim No: 9326419143SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: FBK7656E

 Make & Model:
 HONDA CB400X, 399cc
 Engine No:
 NC47E1006446

 Reg. Date:
 12/01/2016 (Man. Year: 2015)
 Chassis No:
 NC471006431

Colour: Black Odometer: 0 km

Engine Capacity: 399 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 120/60-17 Rear Tyre Size: 160/60-17
Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

**INSPECTION** 

Date of Assignment: 12/10/2021

Bikers Avenue (HQ)

Date Inspected: 19/10/2021 Inspected At: No 1 Bukit Batok Crescent #02-58 WCEGA Plaza

Singapore 658064

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$11,000.00 (EST)

## **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR TYRE	Cut	0.00 F	*-F
2	1	*REAR FENDER MUDFLAP	Crushed	0.00 F	*- F
3	1	*REAR LH SIGNAL LAMP	* Check	0.00 F	*- F
4	1	*REAR RH SIGNAL LAMP	* Check	0.00 F	*-F
5	1	*REAR TAILLAMP	* Check	0.00 F	*- F
6	1	*REAR NUMBER PLATE	Bent	0.00 F	*-F
7	1	*REAR NUMBER PLATE LAMP	Broken	0.00 F	*- F
8	1	*REAR REFLECTOR	Cut	0.00 F	*-F
9	1	*REAR SUB FRAME	* Check	0.00 F	*- F
F=Fra	nchise part.				
			Total Parts (S\$)	0.00	0.00
		Report was unsubmitted	d during this print-out.		

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### **Recommended Labour**

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >