

# XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 201838521G

Vehicle Number : YN 7998E  
Vehicle Model : FUSO CANTER  
Accident Date : 11.10.2021  
Original Reg Date : 26.06.2015

Date : 11.10.2021  
Chassis : FEB71GA10001  
TP Ins. : LONPAC

Xiao Tony

## ESTIMATE

### Special Nett

|       |       |                                               |          |           |      |
|-------|-------|-----------------------------------------------|----------|-----------|------|
| 1     | 1 pc  | TAILAMPS RH cracked                           | 240.00   | 480.00    | 240  |
| 2     | 1 pc  | TAILAMPS PANEL Not Nec                        | 180.00   | 360.00    | x    |
| 1     | 1 pc  | CARGO LIFT PLATFORM Regis                     |          | 8,000.00  | x    |
|       | 1 pc  | CARGO LIFT PLATFORM STICKERS Nec              |          | 350.00    | 180  |
|       | 1 pc  | CARGO LIFT PLATFORM 60KM/H Nec                |          | 20.00     | 15   |
|       | 1 pc  | CARGO LIFT WONG FONG STICKER Nec              |          | 50.00     | ✓    |
|       | 1 pc  | CARGO LIFT PLATFORM DHOLLANDIA Nec            | 900      | 60.00     | ✓    |
| 2     | 1 pc  | CARGO BED LIFTING ARM Cylinder Bracket Bent   | 3,000.00 | 6,000.00  | 1800 |
| 3     | 2 pc  | CARGO BED LIFTING CYLINDER RH Bent            | 5,000.00 | 10,000.00 | 2800 |
| 4     | 2 pc  | CARGO BED TILTING CYLINDER RH Bent            | 5,000.00 | 10,000.00 | 2600 |
| 5     | 1 pc  | CARGO BED SAFETY REINFORCEMENT(CTR) Dented    | 650.00   | 1,300.00  | 650  |
|       | 1 pc  | CARGO BED REINFORCEMENT(CTR)STICKER Nec       | 250.00   | 250.00    | 50   |
| 6     | 2 pcs | SAFETY REINFORCEMENT SIDE RH Dented           | 650.00   | 1,300.00  | 650  |
|       | 1 pcs | SAFETY REINFORCEMENT SIDE NERTA STICKER Nec   |          | 60.00     | +    |
|       | 2 pcs | SAFETY REINFORCEMENT SIDE REFLECTIVE Nec RH   | 85.00    | 170.00    | 50   |
| 7     | 1 pc  | SAFETY REINFORCEMENT LOWER Dented             |          | 850.00    | ✓    |
| 8     | 1 pc  | SAFETY REINFORCEMENT LOWER REFLECTIVE Nec     |          | 150.00    | 80   |
|       | 1 pc  | CARGO BED CHASSIS MEMBER Not Nec              |          | 3,500.00  | x    |
|       | 2 pc  | CARGO BED LIFT PLATFORM SAFETY CHAIN Nec      | 120.00   | 240.00    | x    |
|       | 1 pc  | REAR LIFTING PLATFORM COMPANY STICKER Nec     |          | 450.00    | +    |
|       | 1 pc  | REAR SIDE SLIDING DOOR RH Regis               |          | 3,800.00  | +    |
|       | 1 pc  | REAR SIDE SLIDING DOOR COMPANY STICKER RH Nec |          | 450.00    | 300  |
| 9     | 1 pc  | REAR SIDE SLIDING DOOR WOODEN BOARD Nec       |          | 650.00    | x    |
|       | 2 pc  | REAR SIDE SLIDING DOOR LOCK Nec               | 180.00   | 360.00    | +    |
| 10    | 2 pc  | REAR SIDE PILLAR SUPPORT FRAME RH Bent        | 2,500.00 | 5,000.00  | 1000 |
| 13    | 1 pc  | Rear Number Plate Dented                      |          | 50.00     | 30   |
| 14    | 1 pc  | Rear Number Plate lamp Corrod                 |          | 85.00     | ✓    |
| 15    | 1 pc  | Rear Number Plate Base Bracket Bent           |          | 250.00    | 150  |
| 16    | 1 pc  | Rear tailgate "60km/h" sticker Not Repeated   |          | 30.00     | 15 x |
| total |       |                                               |          | 54,265.00 |      |

11840

### Labour charge

|                         |  |          |      |
|-------------------------|--|----------|------|
| Panel Beating           |  | 2,000.00 | 1000 |
| Spray painting          |  | 2,000.00 | 800  |
| Anti rust               |  | 120.00   | 60   |
| Check Wiring on tailamp |  | 120.00   | 30   |

\$ 58,505.00

1850

Adrian Lj  
1/s 12/10/21.

06 Days.

total: 13530

1/s: 10.8K

10.8K

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: