

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21010468/UVF3E2

Date: 03/11/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/21-423274-CA
Claimant Vehicle No :	GBC6449K	Insured Vehicle No :	FBP3392R
Date of Loss:	10/08/2021	Nature of Claim:	TP
		Claim No:	MSC/V/21-000366

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC6449K	Engine No:	1KD2295066
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Chassis No:	JTFHT02P600115522
Reg. Date:	28/05/2013 (Man. Year: 2013)	Odometer:	208832 km
Colour:	Multi-colour		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,107.90	2,091.32	3,016.58	59.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	1,180.00	960.00	44.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,247.90	3,271.32	3,976.58	54.87
Approved Total (Overridden) (\$\$)		2,600.00		
(\$\$)	7,247.90	2,600.00	4,647.90	64.13
+ GST 7.00/7.00% (\$\$)	507.35	182.00	325.35	64.13
Nett Amount (\$\$)	7,755.25	2,782.00	4,973.25	64.13

INSPECTION

Date of Assignment:	12/10/2021	
Date Inspected:	12/10/2021 Inspected At:	Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 Nov 2021)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC6449K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH FENDER	Repair	1,308.30 F	*- FL
2	1		*REAR RH FENDER OUTER PANEL	Repair	517.00 F	*- FL
3	1		*REAR RH SLIDING DOOR	Badly Dented	1,594.50 F	*1,455.10 FL
4	1		*REAR RH SLIDING DOOR LOCK	Not Necessary	288.10 F	*- FL
5	1		*SET REAR RH CORPORATE ADVERTISEMENT & ARTWORK	Necessary	1,400.00 FS	*1,000.00 FS
					Sub Total (S\$)	5,107.90 2,455.10
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00 363.78
					Total Parts (S\$)	5,107.90 2,091.32

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REPLACE AND TRANSFER SLIDING DOOR PANEL, FITTING AND MECHANISMS	New	80.00	50.00
2	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	1,200.00	600.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	800.00	500.00
4	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	60.00	30.00
Gross Labour Cost (\$\$)			2,140.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >