

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21010470/BUF3E2

Date: 19/11/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001776102
Claimant Vehicle No :	SKR9305L	Insured Vehicle No :	YM1111S
Date of Loss:	09/10/2021	Nature of Claim:	TP
		Claim No:	263816

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR9305L	Engine No:	27191031352574
Make & Model:	MERCEDES-BENZ C180, 1.8 Kompressor (A)	Chassis No:	WDD2040452A681671
Reg. Date:	30/04/2012 (Man. Year: 2012)	Odometer:	263064 km
Colour:	Grey		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,522.10	5,519.29	6,002.81	52.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	1,250.00	2,100.00	62.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,872.10	6,769.29	8,102.81	54.48
Approved Total (Overridden) (\$\$)		5,400.00		
(\$\$)	14,872.10	5,400.00	9,472.10	63.69
+ GST 7.00/7.00% (\$\$)	1,041.05	378.00	663.05	63.69
Nett Amount (\$\$)	15,913.15	5,778.00	10,135.15	63.69

INSPECTION

Date of Assignment:	12/10/2021	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT Singapore 415875
Date Inspected:	13/10/2021 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: Lim Teow Guan

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Nov 2021)
Parts:	143	MERCEDES-BENZ C180 1.8 Kompressor (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR9305L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	1,390.00 F	*1,390.00 FL
2	1		*FRONT BONNET LOCK	Jammed	273.00 F	*273.00 FL
3	2		*FRONT BONNET HINGE L+R	Not Damaged	164.00 F	*- FL
4	2		*FRONT BONNET DAMPER L+R	Not Damaged	348.00 F	*- FL
5	1		*FRONT BONNET INSULATOR	Not Damaged	176.00 F	*- FL
6	20		*FRONT BONNET INSULATOR CLIP	Not Necessary	100.00 F	*- FL
7	2		*FRONT BONNET CATCH L+R	Not Necessary	64.00 F	*- FL
8	1		*FRONT BONNET GRILLE	Broken	649.00 F	*649.00 FL
9	1		*FRONT BUMPER	Dented	982.00 F	*982.00 FL
10	2		*FRONT BUMPER PROTECTOR LHR	Not Damaged	248.00 F	*- FL
11	2		*FRONT BUMPER PROTECTOR CHROME LH	Not Damaged	236.00 F	*- FL
12	2		*FRONT BUMPER BRACKET L+R	Broken	146.30 F	*146.30 FL
13	1		*FRONT BUMPER NOZZLE COVER LH	Not Damaged	72.00 F	*- FL
14	1		*FRONT BUMPER SPONGE	Not Damaged	113.00 F	*- FL
15	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	660.00 F	*- FL
16	2		*FRONT BUMPER SENSOR	Short Circuit	686.00 F	*500.00 FL
17	1		*FRONT BUMPER SENSOR WIRE	Not Damaged	189.00 F	*- FL
18	1		*FRONT BUMPER GRILLE	Broken	78.00 F	*78.00 FL
19	2		*FRONT BUMPER GRILLE LH	Broken	124.80 F	*124.80 FL
20	1		*FRONT BUMPER NUMBER PLATE GARNISH	Broken	63.00 F	*63.00 FL
21	1		*HEADLAMP LH	Broken	1,882.00 F	*1,882.00 FL
22	2		*HEADLAMP PANEL LH	Not Damaged	216.40 F	*- FL
23	1		*FRONT SUPPORT PANEL	Not Damaged	343.00 F	*- FL
24	2		*FRONT SUPPORT PANEL SIDE GARNISH LH	Not Damaged	34.60 F	*- FL
25	1		*AIRCON CONDENSOR	Not Damaged	1,121.00 F	*- FL
26	1		*AIRCON CONDENSOR LIQUID PIPE	Not Damaged	238.00 F	*- FL
27	1		*AIRCON CONDENSOR SUCTION PIPE	Not Damaged	276.00 F	*- FL
28	1		*AIRCON CONDENSOR DISCHARGE PIPE	Not Damaged	221.00 F	*- FL
29	1		*AIRCON CONDENSOR DRYER	Not Damaged	188.00 F	*- FL
30	1		*FRONT NUMBER PLATE	Cut	40.00 FS	*40.00 FS
31	1		*RADIATOR COOLANT	Not Necessary	100.00 FS	*- FS
32	1		*BRAKE FLUID	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,522.10	6,128.10
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	608.81
Total Parts (\$\$)	11,522.10	5,519.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R & R ACCIDENT DAMAGE PARTS, TO CUT / WELD, KNOCK AND REALIGN ACCIDENT AFFECTED AREA	New	1,400.00	600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,200.00	400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	120.00	0.00
4	TO R & R AIRCON CONDENSOR AND REFILL GAS	New	180.00	0.00
5	TO CHECK, DIAGNOSE AND RESET FAULTY CODE	New	350.00	250.00
6	TO CHECK WIRING AND HEAD LAMP FOCUS	New	100.00	0.00
Gross Labour Cost (\$)			3,350.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >