

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong

Date: 12 Nov 2021

Preliminary Advice

Insured Vehicle No	: YM1111S		
TP Vehicle No	: SKR9305L	Accident Date	: 09/10/2021
Make	: MERCEDES-BENZ C180	Assignment Date	: 12/10/2021
Date of Inspection	: 13/10/2021	Est. Duration of Repair	: 5
Inspection At	: MS CAR AUTO PTE LTD (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,872.10
Revised Amount	:S\$	6,769.29
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,769.29
Lump Sum Repair	:S\$	5,400.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	29,000.00
COE / PARF Rebate	:S\$	19,373.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,627.00

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.