

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21010472/KQY3N2**Date:** 25/10/2021**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00060762103

**Claimant Vehicle  
No :** GBD7946E**Insured  
Vehicle No :** GBH4521X

Date of Loss: 10/10/2021

Nature of Claim: TP

Claim  
No: SNM21D205789/C02/LEWLC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBD7946E**Make & Model: MERCEDES-BENZ CITAN 109 CDI VAN, 1.5 EXTRA  
LONG 2 SEATERS (A)

Engine No: K9KB608D454770

Reg. Date: 29/04/2015 (Man. Year: 2015)

Chassis No: WDF4156052U158343

Colour: Black

Odometer: 170086 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 9 mm

Rear Left Side: Yokohama 9 mm

Front Right Side: Yokohama 9 mm

Rear Right Side: Yokohama 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,201.00	1,778.00	423.00	19.22
Miscellaneous Items	80.00	80.00	0.00	0.00
Labour	1,480.00	1,200.00	280.00	18.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,761.00</b>	<b>3,058.00</b>	<b>703.00</b>	<b>18.69</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,400.00</b>		
<b>(S\$)</b>	3,761.00	2,400.00	1,361.00	36.19
<b>+ GST 7.00/7.00% (S\$)</b>	263.27	168.00	95.27	36.19
<b>Nett Amount (S\$)</b>	<b>4,024.27</b>	<b>2,568.00</b>	<b>1,456.27</b>	<b>36.19</b>

**INSPECTION**

Date of Assignment: 12/10/2021 Present Location:

Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 12/10/2021 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial Park A  
Singapore 768761

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 22 Oct 2021)	
<b>Parts:</b>	N/A	MERCEDES-BENZ CITAN 109 CDI VAN 1.5 EXTRA LONG 2 SEATERS (A) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for GBD7946E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC RH TAILGATE	Bent	580.00 F	*580.00 F
2	1		*1 PC RH TAILGATE EMBLEM (109 CDI)	Necessary	35.00 F	*35.00 F
3	1		*1 PC LH TAILGATE THIRD LIGHT	Serviceable	105.00 F	*- F
4	1		*1 PC LH TAILGATE LOGO	Necessary	38.00 F	*38.00 F
5	1		*1 PC LH TAILGATE EMBLEM (CITAN)	Necessary	35.00 F	*35.00 F
6	1		*1 PC LH TAILGATE GLASS	Shattered	230.00 F	*230.00 F
7	1		*1 PC REAR BUMPER	Buckled	650.00 F	*650.00 F
8	1		*1 PC REAR BUMPER REINFORCEMENT	Repair	290.00 F	*- F
9	1		*1 PC LH TAILLAMP	Cut	210.00 F	*210.00 F
10	1		*1 PC LH TAILGATE WIPER NOZZLE	Serviceable	28.00 F	*- F
F=Franchise part.						
					<b>Total Parts (S\$)</b>	<b>2,201.00 1,778.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	<b>1 PC STICKER - 4 PAX</b> (Necessary)	10.00	10.00
2	1	<b>1 PC STICKER - 70KM/H</b> (Necessary)	10.00	10.00
3	1	<b>2 PCS TAILGATE GLASS GUM @30/PC</b> (Necessary)	60.00	60.00
<b>Sub Total (\$\$)</b>			<b>80.00</b>	<b>80.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX LH TAILGATE GLASS	New	80.00	60.00
2	REMOVE & REFIX RH TAILGATE GLASS	New	70.00	60.00
3	REMOVE & REFIX RH TAILGATE ASSY,THIRD BRAKE LIGHTS,REAR WIPER ASSY,LOCK ASSY,REAR BUMPER,TO KNOCK & REPAIR LH TAILGATE,REAR END PANEL & REALIGN THE SAME	New	700.00	500.00
4	PUTTY & RESPRAY ON TAILGATES & ALL AFFECTED AREAS	New	600.00	550.00
5	RUSTPROOFING	New	30.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,480.00</b>	<b>1,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >