

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010473/KQY3N2**Date:** 02/11/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00057542100

Claimant Vehicle No : SKD2237U **Insured Vehicle No :** SKG6919T

Date of Loss: 09/10/2021 Nature of Claim: TP Claim No: SNM21D205760/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKD2237U**

Make & Model: TOYOTA CAMRY, 2.0 (A) Engine No: 1AZE167824

Reg. Date: 01/10/2010 (Man. Year: 2010) Chassis No: MR053BK4107056490

Colour: Metallic Pearl White Odometer: 161704 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Michelin 7 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 7 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,273.11	6,933.02	6,340.09	47.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,830.00	3,420.00	1,410.00	29.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,103.11	10,353.02	7,750.09	42.81
Approved Total (Overridden) (\$\$)		8,200.00		
Nett Amount (\$\$)	18,103.11	8,200.00	9,903.11	54.70

INSPECTION

Date of Assignment: 12/10/2021

Date Inspected: 12/10/2021 Inspected At: Mun Hoong Motor Trading (HQ)
Blk 5033, Ang Mo Kio Industrial Park 2, #01-273
Singapore 569536

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2021)
Parts:	143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD2237U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Buckled	1,257.60 FL	*950.00 FL
2	1		*REAR BOOT LOGO	Necessary	68.60 FL	*68.60 FL
3	1		*REAR BOOT EMBLEM CAMRY	Necessary	89.50 FL	*89.50 FL
4	1		*REAR BOOT EMBLEM 2.0	Necessary	68.60 FL	*68.60 FL
5	2		*REAR BOOT LAMPS-L/R	Cracked	799.10 FL	*799.10 FL
6	1		*REAR BOOT LICENCE PLATE GARNISH	Warped	489.65 FL	*395.20 FL
7	2		*REAR BOOT LICENCE PLATE LAMPS	Serviceable	117.00 FL	*- FL
8	1		*REAR BOOT INNER LOCK	Dented	518.75 FL	*354.90 FL
9	1		*REAR BOOT INNER TRIM	Serviceable	361.35 FL	*- FL
10	12		*REAR BOOT INNER TRIM CLIPS	Not Necessary	66.00 FL	*- FL
11	1		*REAR BOOT LOCK STRIKER	Repair	89.95 FL	*- FL
12	2		*REAR BOOT HINGES-L/R	Repair	379.00 FL	*- FL
13	2		*REAR BOOT STOPPERS	Serviceable	21.00 FL	*- FL
14	1		*REAR BUMPER	Bent	652.50 FL	*566.10 FL
15	1		*REAR BUMPER REFLECTORS	O/s Cracked	179.90 FL	*89.95 FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	577.43 FL	*392.20 FL
17	2		*REAR BUMPER SIDE HOLDERS-L/R	Distorted	137.10 FL	*137.10 FL
18	2		*REAR BUMPER SIDE RETAINERS-L/R	Distorted	179.30 FL	*179.30 FL
19	1		*REAR END PANEL	Bent	859.10 FL	*625.00 FL
20	1		*REAR END PANEL INNER MEMBER	Repair	424.50 FL	*- FL
21	1		*REAR END PANEL GARNISH	Distorted	371.65 FL	*295.00 FL
22	1		*REAR FLOOR BOARD	Serviceable	280.60 FL	*- FL
23	1		*REAR FLOOR COMPARTMENT PANEL	Bent/Buckled	781.90 FL	*781.90 FL
24	1		*REAR FENDERS-L/R	O/s Buckled	2,027.00 FL	*925.00 FL
25	1		*REAR FENDER INNER TRIMS-L/R	O/s Deformed	1,133.90 FL	*358.00 FL
26	2		*REAR FENDER INNER SHIELDS-L/R	Serviceable	322.86 FL	*- FL
27	1		*REAR FENDER INNER TRIM CLIPS (10 Pcs)	Necessary (5 Pcs only)	55.00 FL	*27.50 FL
28	1		*REAR EXHAUST SILENCER	Repair	819.65 FL	*- FL
29	1		*REAR EXHAUST CHROME PIPE	Repair	189.60 FL	*- FL
30	2		*REAR EXHAUST MOUNTINGS	Serviceable	57.60 FL	*- FL
31	1		*REAR EXHAUST INSULATOR	Serviceable	120.30 FL	*- FL
32	2		*REAR TAILLAMPS-L/R	Cracked	1,167.20 FL	*1,070.00 FL
33	1		*REAR TAILLAMP PANELS-L/R	O/s Bent	483.10 FL	*241.55 FL
34	1		*REAR SMART KEYLESS ANTENNA	Serviceable	192.60 FL	*- FL
35	1		*REAR WINDSCREEN MOULDING	Necessary	181.92 FL	*181.92 FL
36	1		*REAR SIDE CHASSIS MEMBER-RH	Repair	561.90 FL	*- FL
37	1		*SET REAR BUMPER CLIP	Necessary	35.00 FS	*35.00 FS
38	1		*SET REAR REVERSE SENSOR	Dented	280.00 FS	*200.00 FS
39	1		*REAR REVERSE CAMERA	Serviceable	450.00 FS	*- FS
40	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
41	1		*REAR NO PLATE	Serviceable	50.00 FS	*- FS
42	1		*SET REAR FLOOR PANEL SOUND PROOFING	Necessary	120.00 FS	*80.00 FS
43	1		*REAR BOOT W/STRIP (50%)	Dented/Cut	196.08 FS	*130.71 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 17,293.79 9,082.13

Report was unsubmitted during this print-out.

11/2/21, 8:59 AM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					4,020.68	2,149.11
Total Parts (S\$)					13,273.11	6,933.02
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	80.00	20.00
2	TO REMOVE,REFIX REAR WINDSCREEN	New	180.00	120.00
3	TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	100.00
4	TO REMOVE,REFIX REAR REVERSE SENSOR/CAMERA	New	100.00	60.00
5	TO REMOVE,REFIX REAR EXHAUST	New	100.00	0.00
6	TO RESPRAY UNDERCOATING	New	150.00	120.00
7	TO RESPRAY PAINTING AND ETC	New	1,600.00	1,200.00
8	PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS	New	2,500.00	1,800.00
Gross Labour Cost (\$\$)			4,830.00	3,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >