

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AXA17008465/SGA3Q2-1
Date: 25/11/2021REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	GA040353
Claimant Vehicle No :	SKZ8790H	Insured Vehicle No :	SGA7842C
Date of Loss:	25/04/2017	Nature of Claim:	TP
		Claim No:	C0431633

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ8790H		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No:	HIDDEN
Reg. Date:	11/04/2008 (Man. Year: 2008)	Chassis No:	MR053ZEE106101616
Colour:	Silver	Odometer:	184930 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	RIVERA 6 mm	Rear Left Side:	RADAR 6 mm
Front Right Side:	RIVERA 6 mm	Rear Right Side:	RADAR 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,176.22	2,135.45	1,040.77	32.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	1,220.00	200.00	14.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,596.22	3,355.45	1,240.77	27.00
Approved Total (Overridden) (S\$)		2,700.00		

Nett Amount (S\$)	4,596.22	2,700.00	1,896.22	41.26
+ Car Rental (6.0 x S\$85.70/day) (S\$)		514.20		
Nett Liability (S\$)		3,214.20		
Global Sum Settlement (S\$)		3,200.00		

INSPECTION

Date of Assignment: 28/04/2017

Date Inspected: 03/05/2017

Estimated Period of Repair: 4.0 days

Inspected At: Supreme Auto Service Pte Ltd (HQ)
176 Sin Ming Drive #02-01, Sin Ming Autocare
Singapore 575721

Adjuster: Sebastian Yeang Wai Keen**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Mar 2020)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ8790H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR PROTECTOR (CONSISTENT)	Cut	208.30 FL	*208.30 FL
2	1		*REAR DOOR (CONSISTENT)	Dented	1,293.80 FL	*1,100.00 FL
3	1		*REAR DOOR PROTECTOR (CONSISTENT)	Cut	175.90 FL	*175.90 FL
4	1		*REAR DOOR REGULATOR GEAR (CONSISTENT)	Bent	369.70 FL	*369.70 FL
5	1		*REAR DOOR REGULATOR MOTOR (CONSISTENT)	Not Necessary	468.90 FL	*- FL
6	1		*REAR SHOCK ABSORBER (CONSISTENT)	Not Necessary	138.50 FL	*- FL
7	1		*REAR BUMPER (CONSISTENT)	Broken	437.20 FL	*437.20 FL
8	1		*REAR BUMPER SIDE RETAINER (CONSISTENT)	Broken	89.50 FL	*89.50 FL
9	1		*SIDE KIT (LEFT) (CONSISTENT)	Repair	586.50 FL	*- FL
10	1		*ALLY RIM (CONSISTENT)	Cut	350.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,118.30	2,730.60
- List Item Discount on L Items 25.00/25.00% (S\$)	942.08	595.15
Total Parts (S\$)	3,176.22	2,135.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE,KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS	New	600.00	500.00
2	TO SPRAY PAINTING ON AFFECTED AREAS	New	600.00	600.00
3	TO TRANSFER DOOR ACCESSORIES	New	90.00	50.00
4	TO REMOVE AND INSTALL REAR UNDERCARRIAGE PARTS TO ENABLE REPAIR	New	80.00	20.00
5	TO REPLACE ALLOY RIM & PERFORM WHEEL BALANCING	New	50.00	50.00
Gross Labour Cost (\$)			1,420.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >