

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21010475/R1UY3E2

**Date:** 05/11/2021

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00033142104  
Claimant Vehicle No: SMN9161G Insured Vehicle No: GBD7243A  
Date of Loss: 10/10/2021 Nature of Claim: TP Claim No: SNM21D205788/C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN9161G**  
Make & Model: HONDA CITY, 1.5 V CVT (A) Engine No: L15Z16201256  
Reg. Date: 11/09/2018 (Man. Year: 2018) Chassis No: MRHGM6670KT000114  
Colour: Grey Odometer: 24126 km  
Engine Capacity: 1497 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 175/65R15 Rear Tyre Size: 175/65R15  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,071.40	1,071.40	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,690.00	1,130.00	560.00	33.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,761.40</b>	<b>2,201.40</b>	<b>560.00</b>	<b>20.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,750.00</b>		
<b>(S\$)</b>	2,761.40	1,750.00	1,011.40	36.63
<b>+ GST 7.00/7.00% (S\$)</b>	193.30	122.50	70.80	36.63
<b>Nett Amount (S\$)</b>	<b>2,954.70</b>	<b>1,872.50</b>	<b>1,082.20</b>	<b>36.63</b>

### INSPECTION

Date of Assignment: 12/10/2021  
Date Inspected: 18/10/2021 Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ)  
38 Toh Guan Road East, #01-57, Enterprise Hub  
Singapore 608581  
Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD RASUL

**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 05 Nov 2021)

**Parts:** 143      HONDA CITY 1.5 V CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMN9161G)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER LH	Buckled	1,064.00 FL	*1,064.00 FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	119.00 FL	*119.00 FL
3	1		*REAR BUMPER (NPA)	Repair	0.00 FL	*- FL
4	1		*REAR FENDER SHIELD CLIPS LH	Necessary	25.00 FS	*25.00 FS
5	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
6	1		*REAR FENDER SEALANT LH	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>1,308.00</b>	<b>1,308.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	236.60	236.60
<b>Total Parts (\$)</b>	<b>1,071.40</b>	<b>1,071.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	600.00	400.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	600.00	400.00
3	TO REMOVE / REFIX / REPLACE WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	30.00	0.00
4	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	30.00	30.00
5	TO REMOVE AND REFIT REAR SEAT IN ORDER IN REPAIR	New	100.00	60.00
6	TO REMOVE AND REFIT ROOTS LINING & UPHOLSTERY GARNISH	New	100.00	60.00
7	TO REMOVE AND REPLACE REAR WINDSCREEN	New	150.00	120.00
8	WHEEL ALIGNMENT	New	80.00	60.00
			<b>Gross Labour Cost (\$\$)</b>	<b>1,690.00</b>
				<b>1,130.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >