

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21010479/ATY3N2**Date:** 24/01/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00109312106		
<b>Claimant Vehicle No :</b>	SKM274C	<b>Insured Vehicle No :</b>	GBA6198U		
Date of Loss:	11/10/2021	Nature of Claim:	TP	Claim No:	SNM21D205787/C02/THAMYL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKM274C</b>		
Make & Model:	MERCEDES-BENZ A200, 1.3 (A)	Engine No:	27091030314160
Reg. Date:	16/01/2014 (Man. Year: 2013)	Chassis No:	WDD1760432J218756
Colour:	Black	Odometer:	84663 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,519.98	4,048.19	2,471.79	37.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,920.00	1,030.00	1,890.00	64.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>9,439.98</b>	<b>5,078.19</b>	<b>4,361.79</b>	<b>46.21</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,000.00</b>		
<b>(\$\$)</b>	9,439.98	4,000.00	5,439.98	57.63
<b>+ GST 7.00/7.00% (\$\$)</b>	660.80	280.00	380.80	57.63
<b>Nett Amount (\$\$)</b>	<b>10,100.78</b>	<b>4,280.00</b>	<b>5,820.78</b>	<b>57.63</b>

**INSPECTION**

Date of Assignment:	15/10/2021		
Date Inspected:	13/10/2021	Inspected At:	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921
Estimated Period of Repair:	4.0 days		

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jan 2022)
<b>Parts:</b>	144	MERCEDES-BENZ A200 1.3 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKM274C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR OUTER MOULDING	Not Necessary	158.00 FL	*- FL
2	1		*REAR RH DOOR	Buckled	1,880.85 FL	*1,880.85 FL
3	1		*REAR RH DOOR GLASS GUIDE CHANNEL SEAL	Cut	193.00 FL	*193.00 FL
4	1		*REAR RH DOOR INNER INSULATOR PADDING	Not Necessary	46.00 FL	*- FL
5	1		*REAR RH DOOR INNER TRIM BOARD	Deformed	1,060.00 FL	*1,060.00 FL
6	1		*REAR RH DOOR LOWER HINGE	Not Necessary	122.10 FL	*- FL
7	1		*REAR RH DOOR OUTER MOULDING	Not Necessary	162.00 FL	*- FL
8	1		*REAR RH DOOR UPPER HINGE	Damaged	125.45 FL	*125.45 FL
9	1		*REAR RH DOOR VERTICAL GARNISH	Not Necessary	105.00 FL	*- FL
10	1		*REAR RH DOOR WEATHER STRIP SEAL	Necessary	349.80 FL	*349.80 FL
11	1		*RH SIDE CENTER PILLAR	Not Necessary	820.00 FL	*- FL
12	1		*SET FRONT RH DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
13	1		*FRONT RH DOOR OUTER MOULDING WRAP 3M STICKER	Necessary	150.00 FS	*70.00 FS
14	1		*FRONT RH DOOR WRAP 3M STICKER	Necessary	800.00 FS	*300.00 FS
15	1		*SET REAR RH DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
16	1		*REAR RH DOOR OUTER MOULDING WRAP 3M STICKER	Necessary	150.00 FS	*70.00 FS
17	1		*REAR RH DOOR WRAP 3M STICKER	Necessary	800.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>7,022.20</b>	<b>4,409.10</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	502.22	360.91
<b>Total Parts (\$)</b>	<b>6,519.98</b>	<b>4,048.19</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RESET SYSTEM AFTER REPAIR WORKS	New	300.00	0.00
2	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	120.00	0.00
3	TO TRANSFER DOOR GLASS,REGULATOR GEAR,MOTOR,RAILING,CHANNEL TRIM BOARD,MECHANISM LOCK AND HANDLE	New	200.00	80.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	500.00
5	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	400.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,920.00</b>	<b>1,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >