

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 6449G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR RH (N)	BADLY DENTED	1,277.00	1,277.00
1	FRONT DOOR HANDLE RH (N)	NOT NECESSARY	58.00	-
1	FRONT DOOR RUBBER RH (N)	NOT NECESSARY	80.50	-
2	FRONT DOOR HINGE RH @\$35.00 (N)	NOT NECESSARY	70.00	-
1	FRONT DOOR LOCK (N)	NOT NECESSARY	400.00	-
1	FRONT DOOR OUTER MOULDING RH (N)	NOT NECESSARY	80.50	-
1	FRONT WING MIRROR ASSEMBLY RH (N)	NOT NECESSARY	559.00	-
1	FRONT DOOR INNER TRIM BOARD RH (N)	NOT NECESSARY	699.00	-
1	FRONT DOOR POWER WINDOW REGULATOR (N)	NOT NECESSARY	241.00	-
1	FRONT DOOR POWER WINDOW MOTOR (N)	NOT NECESSARY	165.00	-
1	FRONT DOOR TAPE (N)	NECESSARY	15.00	15.00
	LESS 10% DISCOUNT		-364.50	-129.20
			3,280.50	1,162.80
	SPECIAL NETT ITEMS			
8	FRONT DOOR INNER TRIM BOARD CLIPS @\$4.00 (SN)	NOT NECESSARY	32.00	-
			32.00	-
	<u>LABOUR</u>			
	TO CHECKING ELECTRICAL WIRING AND CHECK FUNCTIONS.		60.00	20.00
	TO RESPRAY UNDERCOATING/RUST PROOFING.		100.00	30.00
	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS. }		400.00	200.00
	TO REMOVE,REFIX FRONT DOOR COMPONENTS AND REPLACE FRONT DOOR,CHECK ALIGNMENT. }		400.00	-
	TO RESPRAY PAINTING & ETC.		500.00	300.00
			1,460.00	550.00
	GRAND TOTAL		4,772.50	1,712.80

Report Ref No. CS/SMO21010483/Uvf3n2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS			1,712.80
-----------------------------	--	--	----------

Report Ref No. CS/SMO21010483/Uvf3n2

CHUA KANG SENG

Licensed Appraiser