

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010485/TQY3N2**Date:** 01/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00084272100

Claimant Vehicle No : SMQ9511P **Insured Vehicle No :** SMZ4057U

Date of Loss: 07/10/2021 Nature of Claim: TP Claim No: SNM21D205737/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ9511P**

Make & Model: HYUNDAI AD AVANTE, 1.6 GLS (A) Engine No: G4FGKU476335

Reg. Date: 12/12/2019 (Man. Year: 2019) Chassis No: KMHD841CMLU012689

Colour: White Odometer: 131146 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,408.40	3,658.80	10,749.60	74.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,750.00	2,360.00	4,390.00	65.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,158.40	6,018.80	15,139.60	71.55
Approved Total (Overridden) (\$\$)		4,700.00		
(\$\$)	21,158.40	4,700.00	16,458.40	77.79
+ GST 7.00/7.00% (\$\$)	1,481.09	329.00	1,152.09	77.79
Nett Amount (\$\$)	22,639.49	5,029.00	17,610.49	77.79

INSPECTION

Date of Assignment: 12/10/2021

Date Inspected: 12/10/2021 Inspected At: 56 LOYANG WAY,
#04-04 LOYANG ENTERPRISE BUILDING
REPAIRER: AP AUTOMOTIVE SERVICES PTE LTD

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jun 2022)
Parts:	143	HYUNDAI AD AVANTE 1.6 GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ9511P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Bent	1,905.00 FL	*925.00 FL
2	1		*FRONT DOOR SIDE MIRROR ASSY LH	Not Necessary	242.00 FL	*- FL
3	1		*FRONT DOOR SIDE MIRROR COVER LH	Repair	45.00 FL	*- FL
4	1		*FRONT DOOR LOCK LH	Not Necessary	431.00 FL	*- FL
5	1		*FRONT DOOR LOCK CATCH LH	Not Necessary	76.00 FL	*- FL
6	1		*FRONT DOOR WINDOW MOULDING LH	Not Necessary	131.00 FL	*- FL
7	1		*FRONT DOOR INNER WINDOW MOULDING LH	Not Necessary	58.00 FL	*- FL
8	1		*FRONT DOOR INNER BOARD LH	Not Necessary	455.00 FL	*- FL
9	1		*FRONT DOOR WEATHERSTRIP LH	Necessary	163.00 FL	*163.00 FL
10	1		*FRONT DOOR INNER WEATHERSTRIP LH	Not Necessary	310.00 FL	*- FL
11	1		*B PILLAR LH	Repair	1,419.00 FL	*- FL
12	1		*REAR DOOR LH	Bent	1,879.00 FL	*828.00 FL
13	1		*REAR DOOR WINDOW MOULDING LH	Not Necessary	86.00 FL	*- FL
14	1		*REAR DOOR INNER WINDOW MOULDING LH	Not Necessary	54.00 FL	*- FL
15	1		*REAR DOOR LOCK LH	Not Necessary	437.00 FL	*- FL
16	1		*REAR DOOR LOCK CATCH LH	Not Necessary	76.00 FL	*- FL
17	1		*REAR DOOR INNER BOARD LH	Not Necessary	614.00 FL	*- FL
18	1		*REAR DOOR POWER WINDOW MOTOR LH	Not Necessary	161.00 FL	*- FL
19	1		*REAR DOOR WINDOW REGULATOR LH	Not Necessary	172.00 FL	*- FL
20	2		*REAR DOOR HINGE LH	Not Necessary	142.00 FL	*- FL
21	1		*REAR DOOR WEATHERSTRIP LH	Necessary	106.00 FL	*106.00 FL
22	1		*REAR DOOR INNER WEATHERSTRIP LH	Necessary	117.00 FL	*117.00 FL
23	1		*ROCKER PANEL LH	Bent	1,800.00 FL	*623.00 FL
24	1		*REAR WINDSCREEN MOULDING	Necessary	192.00 FL	*192.00 FL
25	1		*REAR FENDER LH	Bent	1,892.00 FL	*857.00 FL
26	1		*REAR FENDER COWLING LH	Not Necessary	184.00 FL	*- FL
27	1		*REAR ABSORBER LH	Not Necessary	431.00 FL	*- FL
28	1		*REAR KNUCKLE BEARING WITH HUB LH	Not Necessary	454.00 FL	*- FL
29	1		*REAR RIM LH	Dented	844.00 FL	*600.00 FL
30	1		*FRONT DOOR INNER BOARD CLIPS	Necessary	100.00 FS	*20.00 FS
31	1		*REAR DOOR INNER BOARD CLIPS	Necessary	100.00 FS	*20.00 FS
32	1		*ROCKER PANEL SEALANT	Necessary	120.00 FS	*40.00 FS
33	1		*REAR FENDER SEALANT	Necessary	200.00 FS	*40.00 FS
34	1		*REAR FENDER COWLING CLIPS	Necessary	100.00 FS	*10.00 FS
35	1		*REAR TYRE LH	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,896.00	4,541.00
- List Item Discount on L Items 10.00/20.00% (\$\$)	1,487.60	882.20
Total Parts (\$\$)	14,408.40	3,658.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,000.00	1,000.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	900.00
3	TO RNR REAR WINDSCREEN	New	400.00	120.00
4	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	60.00
5	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	80.00
6	TO RNR UNDERCARRIAGE	New	250.00	0.00
7	TO CHECK WHEEL BALANCING	New	250.00	30.00
8	TO CHECK WATER LEAK	New	150.00	20.00
9	TO RNR FUEL TANK	New	250.00	0.00
10	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
11	TO PERFORM RUST PROOFING	New	400.00	30.00
12	TO RNR REAR AND FRONT DOOR MECHANISM	New	600.00	120.00
Gross Labour Cost (\$)			6,750.00	2,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >