

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Name : A & K PACKAGING AND DESIGN TPAXA

Make/Model : TOYOTA HIACE

Vehicle No : GBL 1355 H

Accident date : 05.08.2021

No	DESCRIPTION	Qty	Amount (\$S)
List Items			
1	Bonnet <i>Dented.</i>	1	\$ 1,224.20 <i>853</i>
2	Bonnet hinges @ \$205.80 <i>x 2</i>	2	\$ 411.60 <i>+</i>
3	Bonnet lock <i>Dented</i>	1	\$ 227.00 <i>142</i>
4	Bonnet lock bracket <i>x 2</i>	1	\$ 217.40 <i>+</i>
5	Bonnet emblem <i>Nec</i>	1	\$ 206.10 <i>68</i>
6	Wiper panel garnish <i>ht</i>	1	\$ 686.10 <i>+</i>
7	Wiper panel garnish rubber <i>Nec</i>	1	\$ 329.40 <i>+</i>
8	Front grille <i>Cracked</i>	1	\$ 685.80 <i>581</i>
9	Front support panel <i>Dented</i>	1	\$ 690.00 <i>✓</i>
10	Front support panel inner garnish <i>Cracked</i>	1	\$ 277.60 <i>✓</i>
11	Headlamp @ \$892.90 <i>Cracked</i>	2	\$ 1,785.80 <i>✓</i>
12	Wiper tank <i>Defunct</i>	1	\$ 397.70 <i>192</i>
13	Radiator spare tank <i>x 2</i>	1	\$ 378.00 <i>+</i>
14	Oil cooler <i>Dented</i>	1	\$ 685.40 <i>✓</i>
15	Oil cooler cowling <i>Cracked</i>	1	\$ 330.00 <i>219</i>
16	Oil cooler side garnish <i>x 2</i>	1	\$ 210.00 <i>+</i>
17	Oil cooler side rubber @ \$326.10 <i>x 2</i>	2	\$ 652.20 <i>+</i>
18	Brake master pump <i>Defunct</i>	1	\$ 2,057.40 <i>+</i>
19	Brake oil tank <i>Defunct</i>	1	\$ 674.00 <i>+</i>
20	Brake oil tank wire <i>x 2</i>	1	\$ 446.10 <i>+</i>
21	Front body panel <i>Repis</i>	1	\$ 1,165.30 <i>+</i>
22	Front body panel cover <i>torn</i>	1	\$ 146.50 <i>✓</i>
			\$ 13,883.60
Less 25% Disc			\$ 3,470.90
Total			\$ 10,412.70

Special Nett Items

1	Front grille clips <i>Nec</i>	4	\$ 50.00 <i>20</i>
2	Front support panel inner garnish clips <i>Nec</i>	5	\$ 60.00 <i>20</i>
3	Brake oil (1 tin) <i>x 2</i>	1	\$ 30.00 <i>+</i>
Total			\$ 140.00

Labour Cost

1	Remove & reinstall air con fill in gas	\$ 150.00 <i>120</i>
2	Remove & reinstall brake master pump	\$ 200.00 <i>120</i>
3	Remove & reinstall dashboard	\$ 500.00 <i>+</i>
4	Remove, replace & repair consistent to the accident	\$ 1,800.00 <i>900</i>
5	Respray painting	\$ 1,200.00 <i>700</i>
Total		\$ 3,850.00

LKK Auto Consultants have notified the Repairer of the following:

- To resurvey and repair spray painting
- To replace and repair consistent to the accident
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Grand Total

\$ 14,402.70

total: 6552.72
h/s: 528
058 pms