



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 1355H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET (CONSISTENT)	DENTED	1,224.20	853.00
2	BONNET HINGES @\$205.80 (CONSISTENT)	NOT NECESSARY	411.60	-
1	BONNET LOCK (CONSISTENT)	DAMAGED	227.00	142.00
1	BONNET LOCK BRACKET (CONSISTENT)	NOT NECESSARY	217.40	-
1	BONNET EMBLEM (CONSISTENT)	NECESSARY	206.10	68.00
1	WIPER PANEL GARNISH (CONSISTENT)	CUT	686.10	495.00
1	WIPER PANEL GARNISH RUBBER (CONSISTENT)	NOT NECESSARY	329.40	-
1	FRONT GRILLE (CONSISTENT)	CRACKED	685.80	581.00
1	FRONT SUPPORT PANEL (CONSISTENT)	DENTED	690.00	690.00
1	FRONT SUPPORT PANEL INNER GARNISH (CONSISTENT)	CRACKED	277.60	277.60
2	HEADLAMP @\$892.90 (CONSISTENT)	CRACKED	1,785.80	1,785.80
1	WIPER TANK (CONSISTENT)	DEFORMED	397.70	192.00
1	RADIATOR SPARE TANK (CONSISTENT)	NOT NECESSARY	378.00	-
1	OIL COOLER (CONSISTENT)	DENTED	685.40	685.40
1	OIL COOLER COWLING (CONSISTENT)	CRACKED	330.00	219.00
1	OIL COOLER SIDE GARNISH (CONSISTENT)	NOT NECESSARY	210.00	-
2	OIL COOLER SIDE RUBBER @\$326.10 (CONSISTENT)	NOT NECESSARY	652.20	-
1	BRAKE MASTER PUMP (CONSISTENT)	NOT NECESSARY	2,057.40	-
1	BRAKE OIL TANK (CONSISTENT)	DEFORMED	674.00	95.00
1	BRAKE OIL TANK WIRE (CONSISTENT)	NOT NECESSARY	446.10	-
1	FRONT BODY PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,165.30	-
1	FRONT BODY PANEL COVER (CONSISTENT)	TORN	146.50	146.50
	LESS 25% DISCOUNT		-3,470.90	-1,557.58
			10,412.70	4,672.72
	<u>SPECIAL NETT ITEMS</u>			
4	FRONT GRILLE CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	20.00
5	FRONT SUPPORT PANEL INNER GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	60.00	20.00

Report Ref No. CS/ASM21010487/Aqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BRAKE OIL (1 TIN) (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
			140.00	40.00
	LABOUR			
	REMOVE & REINSTALL AIR CON FILL IN GAS.		150.00	120.00
	REMOVE & REINSTALL BRAKE MASTER PUMP.		200.00	120.00
	REMOVE & REINSTALL DESKBOARD.	NOT NECESSARY	500.00	-
	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BODY PANEL.		1,800.00	900.00
	RESPRAY PAINTING.		1,200.00	700.00
			3,850.00	1,840.00
GRAND TOTAL			14,402.70	6,552.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,200.00

Report Ref No. CS/ASM21010487/Aqy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.