

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS21010491/VTF3N2**Date:** 26/10/2021REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SHB6353L **Insured Vehicle No :** SJU9707G

Date of Loss: 08/10/2021 Nature of Claim: TP Claim No: DMPC2100359H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB6353L**

Make & Model: HYUNDAI AE IONIQ, 1.6 (A) Engine No: G4LEKU211721

Reg. Date: 30/04/2019 (Man. Year: 2019) Chassis No: KMHC851CVKU146269

Colour: Blue Odometer: 240574 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,153.56	1,031.12	122.44	10.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	870.00	650.00	220.00	25.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,023.56	1,681.12	342.44	16.92
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	2,023.56	1,200.00	823.56	40.70
+ GST 7.00/7.00% (S\$)	141.65	84.00	57.65	40.70
Nett Amount (S\$)	2,165.21	1,284.00	881.21	40.70

INSPECTION

Date of Assignment: 12/10/2021

Date Inspected: 12/10/2021 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Oct 2021)
Parts:	143	HYUNDAI AE IONIQ 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB6353L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	459.40 FL	*459.40 FL
2	2		*REAR BUMPER SIDE BRACKET LH/RH	Serviceable	111.60 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*REAR BUMPER CENTRE MOULDING	Scratched	451.25 FL	*451.25 FL
5	1		*REAR BUMPER REFLECTOR RH	Serviceable	41.45 FL	*- FL
6	1		*REAR BUMPER MAT	Cut	50.00 FS	*50.00 FS
7	1		*REAR REVERSE SENSOR	Cut	180.00 FS	*180.00 FS
8	1		*REAR NUMBER PLATE W/HOLD	Cracked	55.00 FS	*55.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,370.70	1,217.65
- List Item Discount on L Items 20.00/20.00% (\$\$)	217.14	186.53
Total Parts (\$\$)	1,153.56	1,031.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	450.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	CHECK WIRING AND LIGHTING	New	60.00	30.00
4	REMOVE/REFIX REVERSE SENSOR	New	60.00	20.00
Gross Labour Cost (\$\$)			870.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >