



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 4477X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	DISTORTED	1,099.10	645.10
1	FRONT BUMPER BEAM (CONSISTENT)	BENT	485.20	322.10
1	FRONT BUMPER SIDE RETAINER O/S (CONSISTENT)	BENT	105.10	66.50
1	FRONT BUMPER FOG LAMP COVER O/S (CONSISTENT)	TWISTED	108.50	81.50
1	SET FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	HEADLAMP O/S (CONSISTENT)	SCRATCHED / CRACKED	1,210.10	781.10
1	HEADLAMP TOP PANEL O/S (CONSISTENT)	TO REPAIR SEE LABOUR	433.10	-
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	1,066.20	-
1	FRONT FENDER O/S (CONSISTENT)	TO REPAIR SEE LABOUR	619.20	-
1	FRONT FENDER INNER SHIELD O/S (CONSISTENT)	DEFORMED / TORN	285.10	241.10
1	SET FRONT FENDER INNER SHIELD CLIPS O/S (CONSISTENT)	NECESSARY	50.00	50.00
1	WIPER WASHER TANK (CONSISTENT)	TORN	281.20	182.40
1	WIPER WASHER TANK MOTOR (CONSISTENT)	NOT NECESSARY	185.00	-
1	FRONT SUPPORT PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	855.10	-
	LESS 50% DISCOUNT		-	-1,209.90
			6,832.90	1,209.90
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	20.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	80.00	-
	TO CONDUCT WHEEL ALIGNMENT .	NOT NECESSARY	80.00	-
	TO RESET & REPROGRAMME SYSTEM.	NOT NECESSARY	80.00	-
	TO REFILL AIR CON GAS.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF HEADLAMP TOP PANEL O/S ,BONNET ,FRONT FENDER O/S AND FRONT SUPPORT PANEL .		750.00	480.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		950.00	700.00
			2,090.00	1,200.00
GRAND TOTAL			8,922.90	2,409.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CC4/ASM21010501/Urs3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.