

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21010508/GVF3E2

**Date:** 27/10/2021

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001545417		
<b>Claimant Vehicle No :</b>	SBS6009M	<b>Insured Vehicle No :</b>	GBK7335G		
Date of Loss:	11/10/2021	Nature of Claim:	TP	Claim No:	263898

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SBS6009M</b>	Engine No:	90292609015504
Make & Model:	MERCEDES-BENZ CITARO O530, 6.4 D (A)	Chassis No:	WEB62808323121903
Reg. Date:	27/05/2011 (Man. Year: 2011)	Odometer:	632876 km
Colour:	Multi-colour		
Engine Capacity:	6374 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,416.00	1,416.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,011.80	1,011.80	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,427.80</b>	<b>2,427.80</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	169.95	169.95	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>2,597.75</b>	<b>2,597.75</b>	<b>0.00</b>	<b>0.00</b>

### INSPECTION

Date of Assignment:	13/10/2021		
Date Inspected:	13/10/2021	Inspected At:	SBS Transit Ltd (AMK) 15 Ang Mo Kio Street 63 Singapore 569117
Estimated Period of Repair:	2.0 days		

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

# REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 27 Oct 2021)	
Parts:	N/A	MERCEDES-BENZ CITARO O530 6.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS6009M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GLASS SIDE NO 7 . GLAZING. O/S	Smashed	457.00 F	*457.00 F
2	1		*SIGNAL LED LIGHT , AMBER	Cracked	36.00 F	*36.00 F
3	1		*TAIL LAMP ASSY RIGHT RR	Cracked	433.00 F	*433.00 F
4	1		*FACE BAR REAR BUMPER W/RR FOGLAMP O/S	Cracked	364.00 F	*364.00 F
5	1		*COVER . OUTSIDE FLAPS . O/S	Cut	126.00 F	*126.00 F
F=Franchise part.						
Total Parts (S\$)					1,416.00	1,416.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CONTRACTORS REPAIR CHARGES	New	750.00	750.00
2	LABOUR	New	184.00	184.00
3	SPRAY PAINTING & SIKAFLESx255	New	77.80	77.80
<b>Gross Labour Cost (S\$)</b>			<b>1,011.80</b>	<b>1,011.80</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >