

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21010509/AQCE2

**Date:** 08/12/2021

### REFERENCE

Insured/Claimant:	YIEU WING FOCK	Policy No:	1800055340		
Date of Loss:	10/10/2021	Nature of Claim:	OD	Claim No:	5467256662SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV6766A		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK059040
Reg. Date:	16/05/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF54JA088886
Colour:	White	Odometer:	55581 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$130,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,639.24	5,876.88	7,762.36	56.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,612.00	2,082.00	8,530.00	80.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>24,251.24</b>	<b>7,958.88</b>	<b>16,292.36</b>	<b>67.18</b>
<b>- Excess (S\$)</b>	<b>1,600.00</b>	<b>1,600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>22,651.24</b>	<b>6,358.88</b>	<b>16,292.36</b>	<b>71.93</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,585.59</b>	<b>445.12</b>	<b>1,140.47</b>	<b>71.93</b>
<b>Nett Amount (S\$)</b>	<b>24,236.83</b>	<b>6,804.00</b>	<b>17,432.83</b>	<b>71.93</b>

### INSPECTION

Date of Assignment:	13/10/2021		
Date Inspected:	12/10/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,504.00 FS	*2,003.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	165.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	223.00 FS	*178.00 FS
4	1		*REAR BUMPER CHROME TRIM	Cut	1,016.00 FS	*812.80 FS
5	1		*REAR BUMPER REFLECTOR - LH	Cut	41.00 FS	*32.56 FS
6	1		*REAR TAIL LIGHT - LH	Cut	1,142.00 FS	*913.60 FS
7	1		*REAR TAIL LIGHT TRIM - LH	Not Necessary	30.00 FS	*- FS
8	1		*REAR BUMPER CARRIER	Not Necessary	940.00 FS	*- FS
9	2		*REAR BUMPER CARRIER SEAL	Not Necessary	28.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	44.00 FS	*- FS
11	2		*REAR BUMPER TOP GUIDE SECTION - LH / RH	Not Necessary	46.00 FS	*- FS
12	1		*REAR BUMPER PARKING AID SENSOR (2PCS)	Missing (1Pc Only)	390.24 FS	*195.12 FS
13	4		*REAR BUMPER PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
14	1		*SET REAR BUMPER WIRING	Not Necessary	671.00 FS	*- FS
15	1		*OPENING BOOTLID CONTROL UNIT	Not Necessary	411.00 FS	*- FS
16	1		*REAR LID KICK SENSOR	Not Necessary	206.00 FS	*- FS
17	1		*AERIAL RETAINER	Not Necessary	26.00 FS	*- FS
18	1		*TELEPHONE AERIAL	Not Necessary	174.00 FS	*- FS
19	1		*TAIL LAMP PANEL	Not Necessary	164.00 FS	*- FS
20	1		*REAR CROSS PANEL	Repair	360.00 FS	*- FS
21	1		*REAR CROSS PANEL REINFORCEMENT	Repair	632.00 FS	*- FS
22	1		*REAR SILENCER - LH	Bent	883.00 FS	*706.40 FS
23	1		*REAR SILENCER - RH	Not Necessary	883.00 FS	*- FS
24	2		*DUAL CLIP	Necessary	104.00 FS	*82.88 FS
25	2		*REAR SILENCER BRACKET	Bent	83.00 FS	*66.40 FS
26	1		*CENTRE SILENCER	Bent	896.00 FS	*716.40 FS
27	1		*CENTRE SILENCER DUAL CLIP	Necessary	59.00 FS	*47.12 FS
28	1		*HEAT SHIELD - LH	Not Necessary	152.00 FS	*- FS
29	1		*HEAD SHIELD - CENTER	Not Necessary	69.00 FS	*- FS
30	1		*EXHAUST CHROME TRIP	Cut	153.00 FS	*122.40 FS
31	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
32	1		*CRAVITY WAX	Not Necessary	140.00 FS	*- FS
33	1		*STONE CHIP TREATMENT	Not Necessary	180.00 FS	*- FS
34	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
35	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 13,639.24 5,876.88

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	480.00	0.00
3	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD REAR END PANELLING AND LHS TAILLAMP PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	500.00
4	TO RESPRAY REAR BUMPER, LHS TAILLAMP PANEL, REAR END PANELLING AND SPARE WHEEL HOUSING	New	3,500.00	550.00
5	TO RENEW BOTH REAR EXHAUST SILENCER AND CENTRE SILENCER. TO ALIGN TO POSITION	New	480.00	480.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,612.00</b>	<b>2,082.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >