

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 2511D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TORN	458.60	458.60
1	REAR BUMPER LOWER EXTENSION RH	TORN	232.00	232.00
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	112.70	112.70
10	REAR BUMPER COVER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR WHEEL RIM RH	CUT	1,555.00	1,555.00
	LESS 25% DISCOUNT		-595.08	-595.08
			1,785.22	1,785.22
	SPECIAL NETT ITEMS			
1	REAR WESTLAKE TYRE RH (SN)	NOT NECESSARY	216.00	-
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADV STICKER RH/LH @\$100.00 (SN)	CUT	200.00	200.00
1	REAR BUMPER ADV STICKER (SN)	NECESSARY	50.00	50.00
			516.00	300.00
	<u>LABOUR</u>			
	PANEL BEATING-REAR FENDER RH.		800.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	30.00
			1,520.00	880.00
	GRAND TOTAL		3,821.22	2,965.22

RECOMMENDED COST OF LUMP SUM REPAIRS		2,300.00
(TO ITS PRE-ACCIDENT CONDITION)		·
(CONFIRMED)		

Report Ref No. NS/INC21010511/T1ucn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.