



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7971B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	COVER-RR BUMPER	DEFORMED	459.40	459.40
1	MOULDING ASSY-RR BUMPER C	DEFORMED	451.25	451.25
10	BUMPER COVER CLIP REAR	NECESSARY	22.00	22.00
1	BEAM-RR BUMPER	NOT NECESSARY	394.80	-
1	MOULDING-REAR BUMPER LWR	CRACKED	155.00	155.00
	LESS 20% DISCOUNT		-296.49	-217.53
			<b>1,185.96</b>	<b>870.12</b>
<b><u>NETT ITEMS</u></b>				
1	VEHICLE NUMBER PLATE REAR (N)	CRACKED	50.00	50.00
	LESS 10% DISCOUNT		-5.00	-5.00
			<b>45.00</b>	<b>45.00</b>
<b><u>SPECIAL NETT ITEMS</u></b>				
1	PROTECTOR MAT (SN)	NECESSARY	50.00	50.00
			<b>50.00</b>	<b>50.00</b>
<b><u>LABOUR</u></b>				
	PANEL BEATING.		400.00	350.00
	SPRAYPAINT CHARGE.		300.00	250.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			<b>780.00</b>	<b>630.00</b>
<b>GRAND TOTAL</b>			<b>2,060.96</b>	<b>1,595.12</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>1,595.12</b>

Report Ref No. NS/INC21010515/T1ucn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.